

www.vabfleetservices.be Date: 30/10/2017 1/4

D5TYMG

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: DIRTY [x] Owner: Mileage : 138846 KM File nr. : Mileage start / arrival: 0 / 01453403 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1CJT289 / WBA1C71010E965159 / E-File nr. : First registration: 14/12/2011 Color: VFS-nr.: **GREY** Make + Model : Fuel type : BMW / 1 **DIESEL** Object nr. : Fuel: 17385 Classification: **Environment Class:** EURO 5 Customer company: Co2: Laga CVBA 117g/km Driver : Remote controls: 2 TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: 1 BER HATCH 116d 116PK Country registration: **BELGIUM**

_		_	
Variant car:		Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:		1	

Metallic paint:

Yes



www.vabfleetservices.be Date: 30/10/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:		[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

11011	tyro			205	_			55			R		16	V
Front	tvre		1	205				55			R		16	V
		[x]	W	idth .			Н	eight			Type		Rim	Index
Wheel RES:	[x]			Tyre:		OK		/	Rim:				Hubcap:	
Wheel DEC.	[11]			True		OV		,	Dim .				/ Hubaan .	
Wheel RR:	[x]	BRII	OGESTONE	Tyre:		OK	[x]	2-4 /	Rim:				Hubcap:	
Wheel FR:	[x]	BRII	OGESTONE	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	Hubcap:	
Wheel RL:	[x]	BRII	OGESTONE	Tyre:		OK	[x]	2-4 /	Rim:				Hubcap:	
Wheel FL:	[x]	BRII	OGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	Hubcap:	

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 30/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] REAR DOOR/RIGHT/REAR DENT

Interior

[x] DASHBORD OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

x] REAR DOOR/LEFT/FRONT DENT

Number Code Description Unit price Depr. Total

1 I 1 i-vab-uitd-01 BEAT OUT DENT 63.00 EUR 63.00 EUR

Others

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

	1	2	3	4	5	6	7	8	9	10
ĺ	63.00	95.00	0	0	0	0	0	0	0	0
ĺ	63.00	95.00	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
158.00	0	0	158.00
NA Deprec. 158.00		BG: 0	HOG: 0
0.00%			

TOTAL 158.00



www.vabfleetservices.be Date: 30/10/2017 4/4

[x] = Status Modification

Pictures: No

ANCES		UNDER CONDITION - VEHICLE WET						
0 min	Waiting time : Reason :	0 min	Towing time : Reason :	0 min				
No			I					
thout VAT								
		Executed by VAB	Fleet Services					
stomer :								
30/10/2017	Hour: 11:31							
et .								
@								
customer								
	No Shout VAT stomer: 30/10/2017	0 min Waiting time : Reason : No	No Waiting time : 0 min Reason :	Waiting time: 0 min Reason: No Hout VAT Executed by VAB Fleet Services stomer: 30/10/2017 Hour: 11:31				