

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 62551 KM |
| File nr. : | 1447520 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| HL8986 / WBAXX110600R36751 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 26/10/2015 |
| VFS-nr. : | | Color : | BLUE |
| Make + Model : | BMW / X4 | Fuel type : | DIESEL |
| Object nr. : | | Fuel : | |
| Classification : | | Environment Class: | |
| Customer company : | PWC | Co2: | g/km |
| Driver : | | Remote controls: | 1 |
| Covering : | LEATHER | Number keys : | 1 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------------|----------------------------|---------|
| VAT over the margin - car: | | Metallic paint: | Yes |
| Variant car: | | Engine size: | 1995 |
| Gear box : | Automaat algemeen | Number of places: | 5 |
| Number of gears: | | Number of doors: | 5 |
| HP: | 190 | kW: | 140 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |

General condition:

| | |
|--------------------------------|---------------------------|
| Original registr. number : OK | Service manual : |
| Cert. of reg. / Part 1: OK [x] | Cert. of conformity : |
| Cert. of reg. copy / Part 2: | Insurance certificate : |
| Warning vest : | Transport licence : |
| Tax certificate : | Navigation CD/SD/DVD |
| Fuel card : | Car radio : OK [x] |
| Mobile phone kit : | Extinguisher : OK [x] |
| First aid kit : OK [x] | Warning triangle : OK [x] |
| Jack, wheelspanner : | Oil level : OK [x] |
| | Filled up : 0 |

Wheels and tyres: Summer tires

| |
|--|
| Wheel FL: [x] PIRELLI Tyre : OK [x] 4-6/ Rim : / Hubcap : |
| Wheel RL : [x] PIRELLI Tyre : OK [x] 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| Wheel FR : [x] PIRELLI Tyre : [x] OK [x] 4-6/ Rim : / Hubcap : |
| Wheel RR : [x] PIRELLI Tyre : OK [x] 4-6/ Rim : / Hubcap : |
| Wheel RES: [x] Tyre : OK / Rim : [x] MISSING/INCOMPLETE / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 245 | 50 | R | 18 | W |
| Rear tyre | 245 | 50 | R | 18 | W |

Remark : RSC

Wheels and tyres:

| |
|---|
| Wheel FL: Tyre : OK / Rim : / Hubcap : |
| Wheel RL : Tyre : OK / Rim : / Hubcap : |
| Wheel FR : Tyre : OK / Rim : / Hubcap : |
| Wheel RR : Tyre : OK / Rim : / Hubcap : |
| Wheel RES: Tyre : OK / Rim : / Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|----------------------------|---------------------------|
| [x] | REAR MUDGUARD/RIGHT/CENTER | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT DOOR/RIGHT/CENTER | DENT |
| [x] | BONNET/LEFT/FRONT | CHIPS |
| [x] | FRONT BUMPER/LEFT | SCRATCH WITH PAINT DAMAGE |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| [x] | REAR BUMPER/LEFT/LEFT | SCRATCH WITH PAINT DAMAGE | | | | | | | | | | | | |
|-------------------|--------------------------|---|-------------------|---------------|-------------|------------|-------------------|------------|------|------------|----------------|-----------------|------------|------------|
| | | <table border="0"> <thead> <tr> <th style="border-top: 1px solid black;">Repair paint - LI</th> <th style="border-top: 1px solid black;">New paint - E</th> <th style="border-top: 1px solid black;">Depr.</th> <th style="border-top: 1px solid black;">Total</th> </tr> </thead> <tbody> <tr> <td style="border-top: 1px solid black;">3 0 LU =0.00 EUR</td> <td style="border-top: 1px solid black;">0 EUR</td> <td style="border-top: 1px solid black;">50 %</td> <td style="border-top: 1px solid black;"></td> </tr> </tbody> </table> | Repair paint - LI | New paint - E | Depr. | Total | 3 0 LU =0.00 EUR | 0 EUR | 50 % | | | | | |
| Repair paint - LI | New paint - E | Depr. | Total | | | | | | | | | | | |
| 3 0 LU =0.00 EUR | 0 EUR | 50 % | | | | | | | | | | | | |
| | | <table border="0"> <thead> <tr> <th style="border-top: 1px solid black;">Number</th> <th style="border-top: 1px solid black;">Code</th> <th style="border-top: 1px solid black;">Description</th> <th style="border-top: 1px solid black;">Unit price</th> <th style="border-top: 1px solid black;">Depr.</th> <th style="border-top: 1px solid black;">Total</th> </tr> </thead> <tbody> <tr> <td style="border-top: 1px solid black;">3</td> <td style="border-top: 1px solid black;">I 1</td> <td style="border-top: 1px solid black;">i-vab-sp-01</td> <td style="border-top: 1px solid black;">SPOTREPAIR</td> <td style="border-top: 1px solid black;">115.56 EUR</td> <td style="border-top: 1px solid black;">115.56 EUR</td> </tr> </tbody> </table> | Number | Code | Description | Unit price | Depr. | Total | 3 | I 1 | i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | 115.56 EUR |
| Number | Code | Description | Unit price | Depr. | Total | | | | | | | | | |
| 3 | I 1 | i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | 115.56 EUR | | | | | | | | | |
| [x] | REAR MUDGUARD/LEFT/FRONT | SCRATCH WITH PAINT DAMAGE | | | | | | | | | | | | |
| | | <table border="0"> <thead> <tr> <th style="border-top: 1px solid black;">Repair paint - LI</th> <th style="border-top: 1px solid black;">New paint - E</th> <th style="border-top: 1px solid black;">Depr.</th> <th style="border-top: 1px solid black;">Total</th> </tr> </thead> <tbody> <tr> <td style="border-top: 1px solid black;">2 5 LU =24.00 EUR</td> <td style="border-top: 1px solid black;">369.84 EUR</td> <td style="border-top: 1px solid black;">50 %</td> <td style="border-top: 1px solid black;">393.84 EUR</td> </tr> </tbody> </table> | Repair paint - LI | New paint - E | Depr. | Total | 2 5 LU =24.00 EUR | 369.84 EUR | 50 % | 393.84 EUR | | | | |
| Repair paint - LI | New paint - E | Depr. | Total | | | | | | | | | | | |
| 2 5 LU =24.00 EUR | 369.84 EUR | 50 % | 393.84 EUR | | | | | | | | | | | |
| [x] | REAR DOOR/LEFT/REAR | SCRATCH WITH PAINT DAMAGE | | | | | | | | | | | | |
| | | <table border="0"> <thead> <tr> <th style="border-top: 1px solid black;">Repair paint - LI</th> <th style="border-top: 1px solid black;">New paint - E</th> <th style="border-top: 1px solid black;">Depr.</th> <th style="border-top: 1px solid black;">Total</th> </tr> </thead> <tbody> <tr> <td style="border-top: 1px solid black;">2 0 LU =0.00 EUR</td> <td style="border-top: 1px solid black;">382.02 EUR</td> <td style="border-top: 1px solid black;">50 %</td> <td style="border-top: 1px solid black;">382.02 EUR</td> </tr> </tbody> </table> | Repair paint - LI | New paint - E | Depr. | Total | 2 0 LU =0.00 EUR | 382.02 EUR | 50 % | 382.02 EUR | | | | |
| Repair paint - LI | New paint - E | Depr. | Total | | | | | | | | | | | |
| 2 0 LU =0.00 EUR | 382.02 EUR | 50 % | 382.02 EUR | | | | | | | | | | | |
| [x] | REAR DOOR/RIGHT/CENTER | SCRATCH WITH PAINT DAMAGE | | | | | | | | | | | | |
| | | <table border="0"> <thead> <tr> <th style="border-top: 1px solid black;">Repair paint - LI</th> <th style="border-top: 1px solid black;">New paint - E</th> <th style="border-top: 1px solid black;">Depr.</th> <th style="border-top: 1px solid black;">Total</th> </tr> </thead> <tbody> <tr> <td style="border-top: 1px solid black;">4 0 LU =0.00 EUR</td> <td style="border-top: 1px solid black;">382.02 EUR</td> <td style="border-top: 1px solid black;">50 %</td> <td style="border-top: 1px solid black;">382.02 EUR</td> </tr> </tbody> </table> | Repair paint - LI | New paint - E | Depr. | Total | 4 0 LU =0.00 EUR | 382.02 EUR | 50 % | 382.02 EUR | | | | |
| Repair paint - LI | New paint - E | Depr. | Total | | | | | | | | | | | |
| 4 0 LU =0.00 EUR | 382.02 EUR | 50 % | 382.02 EUR | | | | | | | | | | | |
| [x] | FRONT BUMPER/RIGHT | SCRATCH WITH PAINT DAMAGE | | | | | | | | | | | | |
| | | <table border="0"> <thead> <tr> <th style="border-top: 1px solid black;">Number</th> <th style="border-top: 1px solid black;">Code</th> <th style="border-top: 1px solid black;">Description</th> <th style="border-top: 1px solid black;">Unit price</th> <th style="border-top: 1px solid black;">Depr.</th> <th style="border-top: 1px solid black;">Total</th> </tr> </thead> <tbody> <tr> <td style="border-top: 1px solid black;">1</td> <td style="border-top: 1px solid black;">I 1</td> <td style="border-top: 1px solid black;">i-vab-sp-01</td> <td style="border-top: 1px solid black;">SPOTREPAIR</td> <td style="border-top: 1px solid black;">115.56 EUR</td> <td style="border-top: 1px solid black;">115.56 EUR</td> </tr> </tbody> </table> | Number | Code | Description | Unit price | Depr. | Total | 1 | I 1 | i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | 115.56 EUR |
| Number | Code | Description | Unit price | Depr. | Total | | | | | | | | | |
| 1 | I 1 | i-vab-sp-01 | SPOTREPAIR | 115.56 EUR | 115.56 EUR | | | | | | | | | |
| | | <table border="0"> <thead> <tr> <th style="border-top: 1px solid black;">Number</th> <th style="border-top: 1px solid black;">Code</th> <th style="border-top: 1px solid black;">Description</th> <th style="border-top: 1px solid black;">Unit price</th> <th style="border-top: 1px solid black;">Depr.</th> <th style="border-top: 1px solid black;">Total</th> </tr> </thead> <tbody> <tr> <td style="border-top: 1px solid black;">1</td> <td style="border-top: 1px solid black;">I 1</td> <td style="border-top: 1px solid black;">i-vab-kunst-01</td> <td style="border-top: 1px solid black;">PLASTICS REPAIR</td> <td style="border-top: 1px solid black;">110.64 EUR</td> <td style="border-top: 1px solid black;">110.64 EUR</td> </tr> </tbody> </table> | Number | Code | Description | Unit price | Depr. | Total | 1 | I 1 | i-vab-kunst-01 | PLASTICS REPAIR | 110.64 EUR | 110.64 EUR |
| Number | Code | Description | Unit price | Depr. | Total | | | | | | | | | |
| 1 | I 1 | i-vab-kunst-01 | PLASTICS REPAIR | 110.64 EUR | 110.64 EUR | | | | | | | | | |

| |
|---------------|
| Pieces |
|---------------|

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 2 | 1 | WHEEL HUL | 72.00 EUR | 50 % | 72.00 EUR |
| 3 | 1 | REFLECTOR L | 15.00 EUR | 50 % | 15.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|--------|---|---|---|---|---|----|
| 226.20 | 847.86 | 130.56 | 382.02 | 0 | 0 | 0 | 0 | 0 | 0 |
| 226.20 | 423.93 | 123.06 | 191.01 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 341.76 | 1244.88 | 0 | 1586.64 |
| HOG: 0 | BG: 2 | | NA Deprec. 964.20 |
| | | | 0.00% |
| | | | TOTAL 964.20 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 17/10/2017 Hour : 10:14 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |