

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	100789 KM
File nr. :	1453412	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FDW864 / WBA3K110X0F824416 /		yr of constructionr :	/
E-File nr. :		First registration :	03/06/2013
VFS-nr. :		Color :	BROWN
Make + Model :	BMW / 3 TOURING	Fuel type :	DIESEL
Object nr. :	713891	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	PALL BVBA	Co2:	119g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 TOURING 318d 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD OK [x]
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN	Tyre : OK [x] 2-4/	Rim : /	Hubcap :
Wheel RL : [x] MICHELIN	Tyre : OK [x] 2-4/	Rim : /	Hubcap :
Wheel FR : [x] MICHELIN	Tyre : [x] OK [x] 2-4/	Rim : /	Hubcap :
Wheel RR : [x] MICHELIN	Tyre : OK [x] 2-4/	Rim : /	Hubcap :
Wheel RES: [x]	Tyre : OK /	Rim : /	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre : OK /	Rim : /	Hubcap :
Wheel RL :	Tyre : OK /	Rim : /	Hubcap :
Wheel FR :	Tyre : OK /	Rim : /	Hubcap :
Wheel RR :	Tyre : OK /	Rim : /	Hubcap :
Wheel RES:	Tyre : OK /	Rim : /	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT DOOR/RIGHT/CENTER	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		318.35 EUR		50 %	318.35 EUR

[x]	BONNET/CENTER/LEFT	OTHER DAMAGES				
			Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR		0 EUR		50 %	24.00 EUR

[x]	FRONT BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR		211.80 EUR		50 %	211.80 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	ISOLATIE	40.00 EUR	50 %	40.00 EUR

1	2	3	4	5	6	7	8	9	10
64.00	318.35	211.80	0	0	0	0	0	0	0
32.00	159.18	105.90	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	594.15	0	594.15
HOG: 0	BG: 0		NA Deprec. 297.08
			0.00%
			TOTAL 297.08

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 02/11/2017 Hour : 09:25 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	