

Date: www.vabfleetservices.be 25/10/2017 1/5

D3DQPD

[] NOT EXECUTED [X] EFFECTIVE [X] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 184956 KM File nr. : Mileage start / arrival: 0 / 01451470 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FLC529 / WAUZZZ8K7DA217128 / E-File nr. : First registration: 02/08/2013 Color: VFS-nr.: **GREY** Make + Model : Fuel type : AUDI / A4 AVANT **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: KINEPOLIS MULTI NV (HASSELT) 116g/km Driver : Remote controls: 2 TISSUE Covering: Number keys: 2[x]Vehicle kind: Seats (minivan): 0 Vehicle type: A4 AVANT TDie 136PK Country registration : **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes			
Variant car:	BREAK	Engine size:	1968			
Gear box :	Manueel	Number of places:	5			
Number of gears:	6	Number of doors:	5			
HP:	136	kW:	100			
Fisc HP		Imported vehicle:				
Animals transported:		Smoked in vehicle:				
Due date vehicle inspection:		Extra set of tires:	No			
		Use:	Unknown			
General condition:						



www.vabfleetservices.be Date: 25/10/2017 2/5

Original registr. number :	OK	Service manual :	OK	
Cert. of reg. / Part 1:		Cert. of conformity :	OK	[x]
Cert. of reg. copy / Part 2:	OK	Insurance certificate :		
Warning vest :	OK	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	
Mobile phone kit :		Extinguisher :	OK	
		Warning triangle :	OK	
First aid kit :	OK	Oil level :	OK	
Jack, wheelspanner :	OK	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre:	OK	4-6 /	Rim:			/	Hubcap:
Wheel RL:	[x]	GOODYEAR	Tyre:	OK [2	x] >6/	Rim:			/	Hubcap:
Wheel FR:	[x]	UNIROYAL	Tyre:	OK	4-6 /	Rim:	[x]	WHEEL SCRATCHED	/	Hubcap:
Wheel RR:	[x]	GOODYEAR	Tyre:	OK [x] >6/	Rim:			/	Hubcap:
Wheel RES:	[x]	CONTINENTAL	Tyre:	OK [2	x] 2-4/	Rim:			/	Hubcap:

	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



3 I 1

i-vab-sp-01

SPOTREPAIR

APPRAISAL

Date: 25/10/2017 www.vabfleetservices.be 3/5

	ATUS: ACCEPTABLE / U	JSAGE DAMA	.GE		
Вос	dywork \& windows				
x]	REAR DOOR/CENTER/RIGHT		SCRATCH (WITHOUT PAINT DAMAGE	POL.	
κ]	REAR DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE		
κ]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE		
:]	ROOF/FRONT/LEFT/CENTER		DENT		
]	ROOF/FRONT/CENTER/RIGHT		CHIPS		
k]	FRONT MUDGUARD/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE		
k]	BONNET/CENTER/RIGHT		CHIPS		
x]	FRONT MUDGUARD/RIGHT/FRONT		SCRATCH (WITHOUT PAINT DAMAGE)	
	FRONT BUMPER/LEFT/SIDE		SCRATCH (WITHOUT PAINT DAMAGE	TE POLIJSTEN	
x]	BONNET/CENTER/LEFT/FRONT		CHIPS		
nte	erior				
x]	BOOT LID IN		SCRATCHED		
٩cc	cessories and others				
x]	OUTSIDE MIRROR RIGHTHAND SIDE		SCRATCH WITH PAINT DAMAGE		
ST .	ATUS: NOT ACCEPTAB	LE			
300	dywork \& windows				
x]	REAR BUMPER/SIDE/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
	3 15 LU =72.00 EUR	211.80 EUR		50 %	283.80 EUR
(]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
	3 0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
x]	REAR DOOR/RIGHT/CORNER/BELOW		SCRATCH WITH PAINT DAMAGE	INT.	
	Number Code	Description	Unit price	Depr.	Total

115.56 EUR

115.56 EUR



25/10/2017 www.vabfleetservices.be Date: 4/5 REAR DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE [x] Repair paint - LI New paint - E Depr. **Total** 3 0 LU =0.00 EUR 318.35 EUR 50 % 318.35 EUR [x] WINDSCREEN/CENTER/RIGHT WINDOW DAMAGE Number Code Description Unit price Depr. Total I 1 i-vab-herstr-01 WINDOW REPAIR 58.80 EUR 58.80 EUR FRONT DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE [x] Repair paint - LI New paint - E Depr. Total 3 0 LU =0.00 EUR 318.35 EUR 318.35 EUR 50 % FRONT BUMPER/RIGHT/SIDE SCRATCH WITH PAINT DAMAGE [x] Repair paint - LI New paint - E **Total** Depr. 3 20 LU =96.00 EUR 211.80 EUR 50 % 307.80 EUR Interior STAIN [x] SEAT REAR RIGHT Number Code Description Unit price **Total** Depr. I 1 i-vab-rein-07 CLEANING (PER 15') 14.58 EUR 14.58 EUR 1 2 3 4 5 6 7 8 9 10 58.80 14.58 1652.06 0 0 0 0 0 0 0 58.80 14.58 883.81 0 0 0 0 0 0 0 INNOVATIVE TRADITIONAL **GENERAL** 188.94 1536.50 0 1725.44 HOG: 0 BG: 0 957.19 NA Deprec. 0.00% TOTAL 957.19



www.vabfleetservices.be Date: 25/10/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time :	0 :	W-:4:		IT	0:
Extra 1 me :	0 min	Waiting time: 0 m	ın	Towing time :	0 min
		Reason:		Reason:	
NOT EXECUTED:	No				
Reason:					
Remark :	NAVI OK // CO	ONTROLE OVBH = ZIE VORIG BES	STEK [x]		
Prices in EUR with	hout VAT				
Authorized by customer :			Executed by VAB Fleet Se	rvices	
I SIGN FOR TRANSFE	R OF THE VEHICLE THE DAMAGES MEN	AND DECLAIRE NOT TO BE TIONNED IN THE REPORT OF			
Remark authorized cus	stomer :				
Date :	25/10/2017	Hour: 13:41			
Company :					
Executed by VAB Fleet Services	t				
E-Mail :	@				
Signature authorized by	customer				