

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	69130 KM
<b>File nr. :</b>	1447490	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
HL8293 / WBAXX110100R37094 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	16/10/2015
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	BMW / X4	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	
<b>Customer company :</b>	PWC	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	XDRIVE 20D	<b>Country registration :</b>	LUXEMBOURG

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	SUV	<b>Engine size:</b>	1995
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	190	<b>kW:</b>	140
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

<b>Original registr. number :</b> OK	<b>Service manual :</b>
<b>Cert. of reg. / Part 1:</b> OK [x]	<b>Cert. of conformity :</b> NOK
<b>Cert. of reg. copy / Part 2:</b> NOK	<b>Insurance certificate :</b>
<b>Warning vest :</b> OK [x]	<b>Transport licence :</b>
<b>Tax certificate :</b>	<b>Navigation CD/SD/DVD</b>
<b>Fuel card :</b>	<b>Car radio :</b> OK [x]
<b>Mobile phone kit :</b>	<b>Extinguisher :</b> OK [x]
<b>First aid kit :</b> OK [x]	<b>Warning triangle :</b> OK [x]
<b>Jack, wheelspanner :</b>	<b>Oil level :</b> OK [x]
	<b>Filled up :</b> 0

## Wheels and tyres: Summer tires

<b>Wheel FL:</b> [x] PIRELLI	<b>Tyre :</b> OK [x] 2-4/	<b>Rim :</b> /	<b>Hubcap :</b>
<b>Wheel RL :</b> [x] PIRELLI	<b>Tyre :</b> OK [x] 1.6-2/	<b>Rim :</b> /	<b>Hubcap :</b>
<b>Wheel FR :</b> [x] PIRELLI	<b>Tyre :</b> [x] OK [x] 2-4/	<b>Rim :</b> /	<b>Hubcap :</b>
<b>Wheel RR :</b> [x] PIRELLI	<b>Tyre :</b> OK [x] 1.6-2/	<b>Rim :</b> /	<b>Hubcap :</b>
<b>Wheel RES:</b> [x]	<b>Tyre :</b> OK /	<b>Rim :</b> /	<b>Hubcap :</b>

  

[x]	Width	Height	Type	Rim	Index
Front tyre	245	50	R	18	W
Rear tyre	245	50	R	18	W

**Remark :** PAS DE KIT DE CREVAISON ET DE ROUE DE SECOURS

## Wheels and tyres:

<b>Wheel FL:</b>	<b>Tyre :</b> OK /	<b>Rim :</b> /	<b>Hubcap :</b>
<b>Wheel RL :</b>	<b>Tyre :</b> OK /	<b>Rim :</b> /	<b>Hubcap :</b>
<b>Wheel FR :</b>	<b>Tyre :</b> OK /	<b>Rim :</b> /	<b>Hubcap :</b>
<b>Wheel RR :</b>	<b>Tyre :</b> OK /	<b>Rim :</b> /	<b>Hubcap :</b>
<b>Wheel RES:</b>	<b>Tyre :</b> OK /	<b>Rim :</b> /	<b>Hubcap :</b>

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

**Remark :**

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] REAR DOOR/RIGHT/FRONT DENT
- [x] FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE POIGNEE
- [x] FRONT MUDGUARD/LEFT/REAR SCRATCH WITH PAINT DAMAGE
- [x] BONNET/CENTER/LEFT/FRONT CHIPS

### Interior

- [x] FLOOR FR HOLE
- [x] SEAT REAR L SCRATCHED

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	<b>0</b>
HOG: 0	BG: 2		NA Deprec. <b>0</b>
			0.00%
			<b>TOTAL 0</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 17/10/2017 <b>Hour :</b> 14:22 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	