

D60X91

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|---|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: DIRTY [x] |
| Owner : | | Mileage : | 127494 KM |
| File nr. : | 1453573 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FRF553 / VF7RW9HD8DL520134 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 01/10/2013 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | CITROEN / C5 TOURER | Fuel type : | DIESEL |
| Object nr. : | 12319 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | SIEMENS NV | Co2: | 117g/km |
| Driver : | | Remote controls: | 1 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | C5 TOURER e-HDi Bus.GPS Pl.BMP 113PK Aut | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BREAK | Engine size: | 1560 |
| Gear box : | Automaat algemeen | Number of places: | 5 |
| Number of gears: | | Number of doors: | 5 |
| HP: | 114 | kW: | 84 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | | |
|------------------------------|----|-------------------------|-----------------------|-----|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | OK | [x] | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | | Insurance certificate : | | |
| Warning vest : | | Transport licence : | | |
| Tax certificate : | | Navigation CD/SD/DVD | OK | [x] |
| Fuel card : | | Car radio : | OK | [x] |
| Mobile phone kit : | | Extinguisher : | OK | [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK |
| Jack, wheelspanner : | OK | [x] | Oil level : | OK |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|------|-------|-------|----------|
| Wheel FL: | [x] | UNIROYAL | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RL : | [x] | UNIROYAL | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel FR : | [x] | UNIROYAL | Tyre : | [x] | OK | [x] | 2-4/ | Rim : | / |
| Wheel RR : | [x] | UNIROYAL | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RES: | [x] | | Tyre : | OK | / | | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225 | 60 | R | 16 | V |
| Rear tyre | 225 | 60 | R | 16 | V |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | | | |
|-----|-------------------------|---------------------------|----|--|
| [x] | REAR BUMPER/RIGHT/RIGHT | SCRATCH WITH PAINT DAMAGE | | |
| [x] | ROOF/CENTER/LEFT | DENT | 2X | |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | | |
|-----|---------------------------|---------------------------|----------------------|-------------------|--------------|--------------|
| [x] | REAR DOOR/CENTER/RIGHT | DENT | | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total | |
| 3 | 0 LU =0.00 EUR | 301.68 EUR | | 50 % | 301.68 EUR | |
| [x] | ROOF /FRONT/LEFT/CENTER | DENT | | | | |
| | Number | Code | Description | Unit price | Depr. | Total |
| 2 | 1 | i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |
| [x] | FRONT BUMPER/CENTER/RIGHT | SCRATCH WITH PAINT DAMAGE | | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total | |
| 1 | 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR | |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 1 | 1 | FRONT | 28.80 EUR | 50 % | 28.80 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|-------|--------|---|---|---|---|---|---|----|
| 52.80 | 63.00 | 301.68 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 26.40 | 63.00 | 150.84 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 63.00 | 354.48 | 0 | 417.48 |
| HOG: 0 | BG: 0 | | NA Deprec. 240.24 |
| | | | 0.00% |
| | | | TOTAL 240.24 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 30/10/2017 Hour : 14:18 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |