

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

|                                     |                       |                                 |                               |
|-------------------------------------|-----------------------|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING       | <b>Cleanliness :</b>            | INT: DIRTY [x] EXT: CLEAN [x] |
| <b>Owner :</b>                      |                       | <b>Mileage :</b>                | 168135 KM                     |
| <b>File nr. :</b>                   | 1449614               | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> |                       | <b>Mileag ref. service :</b>    | 0                             |
| 1CBI363 / VSKYBAM20U0028738 /       |                       | <b>yr of constructionr :</b>    | /                             |
| <b>E-File nr. :</b>                 |                       | <b>First registration :</b>     | 11/10/2011                    |
| <b>VFS-nr. :</b>                    |                       | <b>Color :</b>                  | WHITE                         |
| <b>Make + Model :</b>               | NISSAN / NV200        | <b>Fuel type :</b>              | DIESEL                        |
| <b>Object nr. :</b>                 | 52437                 | <b>Fuel :</b>                   |                               |
| <b>Classification :</b>             |                       | <b>Environment Class:</b>       | EURO 4                        |
| <b>Customer company :</b>           | D EN C NV             | <b>Co2:</b>                     | 137g/km                       |
| <b>Driver :</b>                     |                       | <b>Remote controls:</b>         | 1                             |
| <b>Covering :</b>                   | TISSUE                | <b>Number keys :</b>            | 1 [x]                         |
| <b>Vehicle kind :</b>               | TRUCK, LORRY          | <b>Seats (minivan) :</b>        | 0                             |
| <b>Vehicle type :</b>               | NV200 B/F Optima 86PK | <b>Country registration :</b>   | BELGIUM                       |

|                                     |             |                            |         |
|-------------------------------------|-------------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   | No          | <b>Metallic paint:</b>     |         |
| <b>Variant car:</b>                 | BESTELWAGEN | <b>Engine size:</b>        | 1461    |
| <b>Gear box :</b>                   | Manueel     | <b>Number of places:</b>   | 2       |
| <b>Number of gears:</b>             | 5           | <b>Number of doors:</b>    | 5       |
| <b>HP:</b>                          | 86          | <b>kW:</b>                 | 63      |
| <b>Fisc HP</b>                      |             | <b>Imported vehicle:</b>   | No      |
| <b>Animals transported:</b>         | No          | <b>Smoked in vehicle:</b>  | No      |
| <b>Due date vehicle inspection:</b> |             | <b>Extra set of tires:</b> | No      |
|                                     |             | <b>Use:</b>                | Unknown |

**General condition:**

|                              |        |                         |        |
|------------------------------|--------|-------------------------|--------|
| Original registr. number :   | OK     | Service manual :        |        |
| Cert. of reg. / Part 1:      | OK [x] | Cert. of conformity :   |        |
| Cert. of reg. copy / Part 2: |        | Insurance certificate : |        |
| Warning vest :               | OK [x] | Transport licence :     |        |
| Tax certificate :            |        | Navigation CD/SD/DVD    |        |
| Fuel card :                  |        | Car radio :             | OK [x] |
| Mobile phone kit :           |        | Extinguisher :          | OK [x] |
| First aid kit :              | OK [x] | Warning triangle :      | OK [x] |
| Jack, wheelspanner :         |        | Oil level :             | OK [x] |
|                              |        | Filled up :             | 0      |

## Wheels and tyres: Summer tires

|            |     |          |        |     |     |      |       |       |          |          |                    |                    |
|------------|-----|----------|--------|-----|-----|------|-------|-------|----------|----------|--------------------|--------------------|
| Wheel FL:  | [x] | DUNLOP   | Tyre : | OK  | [x] | >6/  | Rim : | /     | Hubcap : | [x]      | MISSING/INCOMPLETE |                    |
| Wheel RL : | [x] | UNIROYAL | Tyre : | OK  | [x] | 4-6/ | Rim : | /     | Hubcap : | [x]      | MISSING/INCOMPLETE |                    |
| Wheel FR : | [x] | DUNLOP   | Tyre : | [x] | OK  | [x]  | >6/   | Rim : | /        | Hubcap : | [x]                | MISSING/INCOMPLETE |
| Wheel RR : | [x] | UNIROYAL | Tyre : | OK  | [x] | 4-6/ | Rim : | /     | Hubcap : | [x]      | MISSING/INCOMPLETE |                    |
| Wheel RES: | [x] |          | Tyre : | OK  |     | /    | Rim : | /     | Hubcap : |          |                    |                    |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 175   | 70     | R    | 14  |       |
| Rear tyre  | 175   | 70     | R    | 14  |       |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |   |          |  |
|------------|--|--------|----|---|-------|---|----------|--|
| Wheel FL:  |  | Tyre : | OK | / | Rim : | / | Hubcap : |  |
| Wheel RL : |  | Tyre : | OK | / | Rim : | / | Hubcap : |  |
| Wheel FR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |  |
| Wheel RR : |  | Tyre : | OK | / | Rim : | / | Hubcap : |  |
| Wheel RES: |  | Tyre : | OK | / | Rim : | / | Hubcap : |  |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] WINDSCREEN/RIGHT CHIPS
- [x] FRONT MUDGUARD/LEFT/Front SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                            |                           |                      |                    |                   |              |              |
|-----|----------------------------|---------------------------|----------------------|--------------------|-------------------|--------------|--------------|
| [x] | REAR DOOR/RIGHT/RIGHT      | DENT                      | MEERDERE             |                    |                   |              |              |
|     |                            | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b>       | <b>Total</b>      |              |              |
| 8   | 0 LU =0.00 EUR             | 301.68 EUR                |                      | 50 %               | 301.68 EUR        |              |              |
| [x] | REAR MUDGUARD/LEFT/CENTER  | DENT                      | MEERDERE             |                    |                   |              |              |
|     |                            | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b>       | <b>Total</b>      |              |              |
| 7   | 0 LU =0.00 EUR             | 308.20 EUR                |                      | 50 %               | 308.20 EUR        |              |              |
| [x] | REAR WHEEL/LEFT            | OTHER DAMAGES             | ONTBREEKT EEN MOER   |                    |                   |              |              |
|     |                            | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b>       | <b>Total</b>      |              |              |
| 10  | 0 LU =0.00 EUR             | 0 EUR                     |                      | 50 %               |                   |              |              |
| [x] | REAR MUDGUARD/RIGHT/CENTER | DENT                      | MEERDERE             |                    |                   |              |              |
|     |                            | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b>       | <b>Total</b>      |              |              |
| 10  | 0 LU =0.00 EUR             | 308.20 EUR                |                      | 50 %               | 308.20 EUR        |              |              |
| [x] | ROOF/CENTER/RIGHT          | DENT                      | +ROESTVORMING        |                    |                   |              |              |
|     |                            | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b>       | <b>Total</b>      |              |              |
| 9   | 0 LU =0.00 EUR             | 481.50 EUR                |                      | 50 %               | 481.50 EUR        |              |              |
| [x] | REAR DOOR/RIGHT/CENTER     | DENT                      | MEERDERE             |                    |                   |              |              |
|     |                            | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b>       | <b>Total</b>      |              |              |
| 10  | 0 LU =0.00 EUR             | 318.35 EUR                |                      | 50 %               | 318.35 EUR        |              |              |
| [x] | FRONT DOOR/LEFT/REAR       | SCRATCH WITH PAINT DAMAGE | +MEERDERE DEUKEN     |                    |                   |              |              |
|     |                            | <b>Repair paint - LI</b>  | <b>New paint - E</b> | <b>Depr.</b>       | <b>Total</b>      |              |              |
| 6   | 0 LU =0.00 EUR             | 318.35 EUR                |                      | 50 %               | 318.35 EUR        |              |              |
| [x] | FRONT BUMPER/LEFT/SIDE     | SCRATCH WITH PAINT DAMAGE |                      |                    |                   |              |              |
|     |                            | <b>Number</b>             | <b>Code</b>          | <b>Description</b> | <b>Unit price</b> | <b>Depr.</b> | <b>Total</b> |
| 5   | I 1                        | i-vab-kunst-01            |                      | PLASTICS REPAIR    | 110.64 EUR        |              | 110.64 EUR   |

|     |                           |                          |                      |              |              |
|-----|---------------------------|--------------------------|----------------------|--------------|--------------|
| [x] | BONNET/CENTER/RIGHT/FRONT | OTHER DAMAGES            | +DEUK                |              |              |
|     |                           | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 4   | 0 LU =0.00 EUR            | 290.08 EUR               |                      | 50 %         | 290.08 EUR   |
| [x] | REAR DOOR/LEFT/LEFT       | DENT                     | MEERDERE             |              |              |
|     |                           | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 8   | 0 LU =0.00 EUR            | 301.68 EUR               |                      | 50 %         | 301.68 EUR   |

## Interior

|     |                     |   |                      |              |              |
|-----|---------------------|---|----------------------|--------------|--------------|
| [x] | FLOOR FL            | HOLE  |                      |              |              |
|     |                     | <b>Repair paint - LI</b>                    | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 3   | 40 LU =192.00 EUR   | 0 EUR                                       |                      |              | 192.00 EUR   |
| [x] | CARPET FL           | HOLE  |                      |              |              |
|     | <b>Number Code</b>  | <b>Description</b>                          | <b>Unit price</b>    | <b>Depr.</b> | <b>Total</b> |
| 3   | I 1 i-vab-inttap-01 | CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)  | 43.92 EUR            |              | 43.92 EUR    |
|     | <b>Number Code</b>  | <b>Description</b>                          | <b>Unit price</b>    | <b>Depr.</b> | <b>Total</b> |
| 3   | I 1 i-vab-inttap-02 | SUPPL REPAIR CARPET                         | 18.00 EUR            |              | 18.00 EUR    |
| [x] | SEAT FL             | HOLE  |                      |              |              |
|     |                     | <b>Repair paint - LI</b>                    | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 3   | 0 LU =0.00 EUR      | 0 EUR                                       |                      | 50 %         |              |
|     |                     | <b>Repair paint - LI</b>                    | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 3   | 20 LU =96.00 EUR    | 0 EUR                                       |                      | 50 %         | 96.00 EUR    |
| [x] | ROOF UPHOLSTERY     | HOLE  |                      |              |              |
|     | <b>Number Code</b>  | <b>Description</b>                          | <b>Unit price</b>    | <b>Depr.</b> | <b>Total</b> |
| 3   | I 2 i-vab-rein-07   | CLEANING (PER 15')                          | 14.58 EUR            |              | 29.16 EUR    |
|     | <b>Number Code</b>  | <b>Description</b>                          | <b>Unit price</b>    | <b>Depr.</b> | <b>Total</b> |
| 3   | I 1 i-vab-intvlr-01 | VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER) | 64.32 EUR            |              | 64.32 EUR    |
| [x] | FLOOR BOOT          | OTHER DAMAGES                               |                      |              |              |
|     |                     | <b>Repair paint - LI</b>                    | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 3   | 0 LU =0.00 EUR      | 0 EUR                                       |                      | 50 %         |              |
|     |                     | <b>Repair paint - LI</b>                    | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 3   | 10 LU =48.00 EUR    | 0 EUR                                       |                      | 50 %         | 48.00 EUR    |

## Accessories and others

|     |                |                          |                      |              |              |
|-----|----------------|--------------------------|----------------------|--------------|--------------|
| [x] | ANTENNA        | BROKEN / CRACKED         |                      |              |              |
|     |                | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
| 3   | 0 LU =0.00 EUR | 0 EUR                    |                      | 50 %         |              |

## Others

### CLEANLINESS INTERIOR

| Number | Code | Description                          | Unit price        | Depr.     | Total     |
|--------|------|--------------------------------------|-------------------|-----------|-----------|
| 1      | I 4  | bestelwagen-cabine-a-vab-rein-05     | CLEANING INTERIOR | 11.47 EUR | 45.88 EUR |
| Number | Code | Description                          | Unit price        | Depr.     | Total     |
| 1      | I 4  | bestelwagen-laadruimte-a-vab-rein-06 | CLEANING INTERIOR | 23.41 EUR | 93.64 EUR |

### HUB CAP FL

|   |                | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
|---|----------------|--------------------------|----------------------|--------------|--------------|
| 2 | 0 LU =0.00 EUR |                          |                      | 50 %         |              |

### HUB CAP REAR L

|   |                | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
|---|----------------|--------------------------|----------------------|--------------|--------------|
| 2 | 0 LU =0.00 EUR |                          |                      | 50 %         |              |

### HUB CAP REAR RIGHT

|   |                | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
|---|----------------|--------------------------|----------------------|--------------|--------------|
| 2 | 0 LU =0.00 EUR |                          |                      | 50 %         |              |

### HUB CAP FR

|   |                | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
|---|----------------|--------------------------|----------------------|--------------|--------------|
| 2 | 0 LU =0.00 EUR |                          |                      | 50 %         |              |

**Pieces**

| Number | Code | Description            | Unit price | Depr. | Total      |
|--------|------|------------------------|------------|-------|------------|
| 2      | 1    | WHEEL CAP              | 30.00 EUR  | 50 %  | 30.00 EUR  |
| 2      | 1    | WHEEL CAP              | 30.00 EUR  | 50 %  | 30.00 EUR  |
| 2      | 1    | WHEEL CAP              | 30.00 EUR  | 50 %  | 30.00 EUR  |
| 2      | 1    | WHEEL CAP              | 30.00 EUR  | 50 %  | 30.00 EUR  |
| 3      | 1    | SEAT UPHOLSTERY TISSUE | 120.00 EUR | 50 %  | 120.00 EUR |
| 3      | 1    | VLOER BESCHERMING      | 100.00 EUR | 50 %  | 100.00 EUR |
| 3      | 1    | ANTENNE                | 15.00 EUR  | 50 %  | 15.00 EUR  |
| 10     | 1    | MOER                   | 10.00 EUR  | 50 %  | 10.00 EUR  |

| 1      | 2      | 3      | 4      | 5      | 6      | 7      | 8      | 9      | 10     |
|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|
| 139.52 | 120.00 | 726.40 | 290.08 | 110.64 | 318.35 | 308.20 | 603.36 | 481.50 | 636.55 |
| 139.52 | 60.00  | 536.90 | 145.04 | 110.64 | 159.18 | 154.10 | 301.68 | 240.75 | 318.28 |

| INNOVATIVE | TRADITIONAL | GENERAL |                      |
|------------|-------------|---------|----------------------|
| 405.56     | 3329.04     | 0       | <b>3734.60</b>       |
| HOG: 0     | BG: 0       |         | NA Deprec. 2166.08   |
|            |             |         | 0.00%                |
|            |             |         | <b>TOTAL 2166.08</b> |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|   |  |   |
|---|--|---|
| <b>Extra Time :</b> 0 min                   | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No<br><b>Reason :</b> |  |   |
| <b>Remark :</b>                             |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 20/10/2017 <b>Hour :</b> 10:46<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| <b>Signature authorized by customer</b><br>  |                                |