

www.vabfleetservices.be Date: 30/10/2017 1/5

D2PDXD

[X] EFFECTIVE [] NOT EXECUTED

No

[X] COLLECTION

[] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	89834
File nr. :	1450954	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FMI012 / WF0KXXGCBKI	DB65160 /	yr of constructionr :	/
E-File nr. :		First registration :	19/08/2013
VFS-nr. :		Color :	BLUE
Make + Model :	FORD / FOCUS	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	WIRELESS TECHNOLOGIES BVBA	Co2:	88g/km
Driver :		Remote controls:	1
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan):	0
Vehicle type :	FOCUS BER ECOnetic Trend 88g 105PK	Country registration :	BELGIUM

		•				
Variant car:		Engine size:	1560			
Gear box :	Manueel	Number of places:	5			
Number of gears:	6	Number of doors:	5			
HP:	105	kW:	77			
Fisc HP		Imported vehicle:				
Animals transported:		Smoked in vehicle:				
Due date vehicle inspection:		Extra set of tires:				
		Use:	Unknown			
General condition:						

Metallic paint:

Yes



www.vabfleetservices.be Date: 30/10/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

		[x]	Width		Height		Type		Rim	Index
Wheel RES:	[x]		Tyre:	OK	/	Rim:		/	Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:	OK	[x] 4-6/	Rim:		/	Hubcap: [x]	SCRATCHED
Wheel FR:	[x]	MICHELIN	Tyre:	x] OK	[x] 2-4/	Rim:		/	Hubcap: [x]	SCRATCHED
Wheel RL:	[x]	MICHELIN	Tyre:	OK	[x] 4-6/	Rim:		/	Hubcap: [x]	MISSING/INCOMPLETE
Wheel FL:	[x]	MICHELIN	Tyre:	OK	[x] 2-4/	Rim:	[x]	/	Hubcap: [x]	SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	Н
Rear tyre	205	55	R	16	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 30/10/2017 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

FRONT DOOR LEFT/REAR SCRATCH WITH PAINT DAMAGE FRONT BUMPERCENTER/LEFT SCRATCH WITH PAINT DAMAGE SLECHTE HERSTELLING THER DAMAGES SLECHTE HERSTELLING THER DAMAGES SLECHTE HERSTELLING THER DAMAGES STAIN	300	dywork \& windows				
REAR DOOR/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE FRONT MUDGUARD/RIGHT/CENTER DENT FRONT BUMPER/RIGHT/CENTER DENT FRONT BUMPER/RIGHT/CENTER OTHER DAMAGES FRONT BUMPER/RIGHT/CENTER OTHER DAMAGES SLECHTE HERSTELLING INTERIOR STAIN CCCESSORIES and others LOGO OTHER DAMAGES STATUS: NOT ACCEPTABLE SODYWORK \& WINDOWS REAR BUMPER /LEFT/CORNER SCRATCH WITH PAINT DAMAGE Repair paint - LI New paint - E Depr. To 1 0 LU = 0.00 EUR STATUS: NOW Depr. To 2 0 LU = 0.00 EUR SONS STATUS: NOW Depr. To 2 0 LU = 0.00 EUR SONS STATUS: NOW Depr. To 3 0 SCRATCH WITH PAINT DAMAGE SCR	.]	REAR DOOR/RIGHT/REAR		DENT		
FRONT DOORLEFT/FEAR SCRATCH WITH PAINT DAMAGE FRONT BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE FRONT BUMPER/RIGHT/CORNER OTHER DAMAGES SEAT FL STAIN SEAT FR STAIN CCCESSORIES and others FOR THE DAMAGES STATUS: NOT ACCEPTABLE SOdywork \& windows FRAR BUMPER/LEFT/CORNER Repair paint - LI New paint - E Depr. To 1 0 LU = 0.00 EUR Repair paint - LI New paint - E OPP. To 2 0 LU = 0.00 EUR Repair paint - LI New paint - E OPP. To 2 0 LU = 0.00 EUR SO % PROVIDED	:]	REAR DOOR/RIGHT/CENTER		DENT		
FRONT MUDGUARD/RIGHT/CENTER FRONT BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE FRONT BUMPER/RIGHT/CORNER OTHER DAMAGES SLECHTE HERSTELLING SEAT FL	κ]	REAR DOOR/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE		
FRONT BUMPER CENTER LEFT SCRATCH WITH PAINT DAMAGE THER DAMAGES SLECHTE HERSTELLING THER DAMAGES SLECHTE HERSTELLING THER DAMAGES STAIN ACCESSORIES AND Others THER DAMAGES STATUS: NOT ACCEPTABLE Bodywork \& windows Ther DAMAGES SCRATCH WITH PAINT DAMAGE SCRATCH WITH PAINT DAMAGE Repair paint - LI New paint - E Depr. To 1 0 LU = 0.00 EUR Pieces To 2 0 LU = 0.00 EUR Pieces	κ]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE		
THE DAMAGES SLECHTE HERSTELLING THE DAMAGES SLECHTE HERSTELLING THE DAMAGES STAIN STAIN ACCESSORIES AND OTHER DAMAGES STATUS: NOT ACCEPTABLE BODYWORK \& WINDOWS THE DAMAGES SCRATCH WITH PAINT DAMAGE REPAIR PAINT - LI New paint - E Depr. To 1 OLU = 0.00 EUR PREPAIR L Repair paint - LI New paint - E Depr. To 2 OLU = 0.00 EUR To To To To To To To To To T	κ]	FRONT MUDGUARD/RIGHT/CENTER		DENT		
SEAT FL	κ]	FRONT BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE		
SEAT FR STAIN Accessories and others LOGO	κ]	FRONT BUMPER/RIGHT/CORNER		OTHER DAMAGES	SLECHTE HER	STELLING
SEAT FR STAIN Accessories and others LOGO	nte	erior				
Accessories and others	κ]	SEAT FL		STAIN		
LOGO OTHER DAMAGES	κ]	SEAT FR		STAIN		
REAR BUMPER / LEFT/CORNER SCRATCH WITH PAINT DAMAGE	\c	cessories and others				
REAR BUMPER /LEFT/CORNER SCRATCH WITH PAINT DAMAGE	κ]	LOGO		OTHER DAMAGES		
Repair paint - LI New paint - E Depr. Total 1 0 LU = 0.00 EUR 211.80 EUR 50 % 211.80 Others HUB CAP REAR L Repair paint - LI New paint - E Depr. Total 2 0 LU = 0.00 EUR 50 % 50 %	ST.	ATUS: NOT ACCEPTA	BLE			
Repair paint - LI New paint - E Depr. Total 1 0 LU = 0.00 EUR 211.80 EUR 50 % 211.80 Others HUB CAP REAR L Repair paint - LI New paint - E Depr. Total 2 0 LU = 0.00 EUR 50 % 50 %	300	dywork \& windows				
1 0 LU = 0.00 EUR 211.80 EUR 50 % 211.80 Others HUB CAP REAR L Repair paint - LI New paint - E Depr. Total	κ]	REAR BUMPER /LEFT/CORNER		SCRATCH WITH PAINT DAMAGE		
Others HUB CAP REAR L Repair paint - LI New paint - E Depr. Total 2 0 LU = 0.00 EUR 50 %			Repair paint - LI	New paint - E	Depr.	Total
HUB CAP REAR L Repair paint - LI New paint - E Depr. Total 2 0 LU = 0.00 EUR 50 %		1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUF
Repair paint - LI New paint - E Depr. To 2 0 LU =0.00 EUR 50 %	Oth	ners				
2 0 LU =0.00 EUR 50 % Pieces		HUB CAP REAR L				
Pieces			Repair paint - LI	New paint - E	Depr.	Total
		2 0 LU =0.00 EUR			50 %	'
Number Code Description Unit price Depr. To	Pie	ces				
		Number Code	Description	Unit price	Depr.	Total



www.vabfleetservices.be Date: 30/10/2017 4/5

1	2	3	4	5	6	7	8	9	10
211.80	30.00	0	0	0	0	0	0	0	0
105.90	15.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	241.80	0		241.80
HOG: 0	BG: 0		NA Deprec.	120.90
			0.00%	
			TOTAL	120.90



www.vabfleetservices.be Date: 30/10/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMS	TANCES		NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time: 0 min Reason:			Towing time : Reason :	0 min		
NOT EXECUTED : Reason :	No	.						
Remark:								
Prices in EUR v	vithout VAT							
Authorized by customer :				Executed by VAB F	leet Services			
Remark authorized	customer :							
Date :	30/10/2017	Hour :	16:10					
Company : Executed by VAB F Services	leet							
E-Mail:	@							
Signature authorized	by customer							