

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	169811 KM
File nr. :	1452656	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
UE6412 / VF30URHE8ES140750 /		yr of constructionr :	/
E-File nr. :		First registration :	24/07/2014
VFS-nr. :		Color :	BLUE
Make + Model :	PEUGEOT / 3008	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	1
Covering :	LEATHER	Number keys :	1 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1997
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]	GOODYEAR	Tyre :	OK	[x]	>6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	M+S
Rear tyre	225	50	R	17	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	DENT
[x]	REAR DOOR/CENTER/RIGHT	DENT
[x]	REAR MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT

Interior

[x]	BOOT IN L	SCRATCHED
[x]	BOOT IN R	SCRATCHED

Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	-------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
5	15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR
[x]	REAR MUDGUARDL/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	258.28 EUR		50 %	258.28 EUR
[x]	REAR MUDGUARD/LEFT/CENTER		DENT		
	Number Code	Description	Unit price	Depr.	Total
9	I 1 i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR		97.80 EUR
[x]	REAR THRESHOLD/LEFT/REAR		OTHER DAMAGES		
		Repair paint - LI	New paint - E	Depr.	Total
10	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR
[x]	REAR DOOR/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x]	REAR DOOR/RIGHT/REAR		DENT			
		Repair paint - LI	New paint - E	Depr.	Total	
6	15 LU =72.00 EUR	318.35 EUR		50 %	390.35 EUR	
[x]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR	
[x]	BONNET/CENTER/LEFT		OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total	
2	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR	
[x]	FRONT BUMPER/LEFT/CORNER		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
3	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR	
	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Interior

[x]	BOOT LID IN		CARVED			
		Repair paint - LI	New paint - E	Depr.	Total	
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR	

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total	
7	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR	

Others

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
8	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

	Number	Code	Description	Unit price	Depr.	Total
8	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

	Number	Code	Description	Unit price	Depr.	Total
8	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
8	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	KOFFERBEKLEDING	50.00 EUR	50 %	50.00 EUR
2	1	ISOLATIE	75.00 EUR	50 %	75.00 EUR
3	1	BUMPER GRID	35.00 EUR	50 %	35.00 EUR
4	1	SIDE PROTECTION	14.40 EUR	50 %	14.40 EUR
5	1	REAR BUMPER	343.20 EUR	50 %	343.20 EUR
5	1	CHROOM	150.00 EUR	50 %	150.00 EUR
7	1	MIRROR	120.00 EUR	50 %	120.00 EUR

1	2	3	4	5	6	7	8	9	10
74.00	171.00	198.56	651.10	823.48	390.35	168.00	380.00	97.80	48.00
37.00	85.50	157.06	325.55	411.74	195.18	84.00	380.00	97.80	24.00

INNOVATIVE	TRADITIONAL	GENERAL	
593.36	2408.93	0	3002.29
HOG: 0	BG: 0		NA Deprec. 1797.82
			0.00%
			TOTAL 1797.82

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 31/10/2017 Hour : 09:17 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	