

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|------------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 88109 KM |
| File nr. : | 1452667 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1EBZ331 / VF30U9HR8CS233552 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 16/10/2012 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | PEUGEOT / 3008 | Fuel type : | DIESEL |
| Object nr. : | 48506 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | TMVW CVBA | Co2: | 117g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | | Seats (minivan) : | 0 |
| Vehicle type : | 3008 Allure STT FAP BMP 112PK Aut. | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | | Engine size: | 1560 |
| Gear box : | Automaat algemeen | Number of places: | 5 |
| Number of gears: | | Number of doors: | 5 |
| HP: | 112 | kW: | 82 |
| Fisc HP | | Imported vehicle: | No |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | | |
|------------------------------|----|-----------------------|-------------------------|-----|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | | Transport licence : | | |
| Tax certificate : | | Navigation CD/SD/DVD | | |
| Fuel card : | | Car radio : | OK | [x] |
| Mobile phone kit : | | Extinguisher : | OK | [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK |
| Jack, wheelspanner : | OK | [x] | Oil level : | OK |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|------|-------|-------|--------------------------------|
| Wheel FL: | [x] | KLÉBER | Tyre : | OK | [x] | >6/ | Rim : | / | Hubcap : |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : |
| Wheel FR : | [x] | KLÉBER | Tyre : | [x] | OK | [x] | >6/ | Rim : | [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK | [x] | 4-6/ | Rim : | / | Hubcap : |
| Wheel RES: | [x] | KLÉBER | Tyre : | OK | [x] | >6/ | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225 | 50 | R | 17 | V |
| Rear tyre | 225 | 50 | R | 17 | V |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/RIGHT/REAR SCRATCH WITH PAINT DAMAGE
- [x] FRONT DOOR/LEFT/REAR SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT MUDGUARD/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | | |
|-----|---------------------------|--------------------------|---------------------------|-------------------|--------------|--------------|
| [x] | REAR BUMPER/RIGHT/RIGHT | | DENT | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total | |
| 3 | 15 LU =72.00 EUR | 0 EUR | | 50 % | 72.00 EUR | |
| [x] | REAR DOOR/CENTER/LEFT | | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total | |
| 2 | 0 LU =0.00 EUR | 301.68 EUR | | 50 % | 301.68 EUR | |
| [x] | REAR MUDGUARD/RIGHT/FRONT | | DENT | | | |
| | Number | Code | Description | Unit price | Depr. | Total |
| 1 | I 1 | i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |

Others

RIM FRONT RIGHT

| | | | | | | |
|---|---------------|-------------------|--------------------|-------------------|--------------|--------------|
| | Number | Code | Description | Unit price | Depr. | Total |
| 4 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | | 95.00 EUR |

Pieces

| | | | | | | |
|---|---------------|-------------|--------------------|-------------------|--------------|--------------|
| | Number | Code | Description | Unit price | Depr. | Total |
| 3 | 1 | REAR BUMPER | | 343.20 EUR | 50 % | 343.20 EUR |
| | Number | Code | Description | Unit price | Depr. | Total |
| 3 | 1 | REAR LIGHT | | 30.00 EUR | 50 % | 30.00 EUR |

| | | | | | | | | | |
|----------|----------|----------|----------|----------|----------|----------|----------|----------|-----------|
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| 63.00 | 301.68 | 445.20 | 95.00 | 0 | 0 | 0 | 0 | 0 | 0 |
| 63.00 | 150.84 | 222.60 | 95.00 | 0 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 158.00 | 746.88 | 0 | 904.88 |
| HOG: 0 | BG: 0 | | NA Deprec. 531.44 |
| | | | 0.00% |
| | | | TOTAL 531.44 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 26/10/2017 Hour : 14:45 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |