

www.vabfleetservices.be Date: 31/10/2017 1/4

D6131T

[X] EFFECTIVE [] NOT EXECUTED

[X] COLLECTION

[] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner:		Mileage :	112659 KM
File nr. :	1453578	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FDE230 / WVWZZZ1KZDW	7570218 /	yr of constructionr :	/
E-File nr. :		First registration :	29/05/2013
VFS-nr. :		Color :	BROWN
Make + Model :	VOLKSWAGEN / GOLF PLUS	Fuel type :	DIESEL
Object nr. :	12103	Fuel :	
Classification:		Environment Class:	EURO 5
Customer company :	Bisnode Belgium nv	Co2:	129g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	GOLF PLUS Highline DSG DPF 105PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:	,	<u> </u>	



www.vabfleetservices.be Date: 31/10/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

		[x]	Width		Height			Туре		Rim	Index
Wheel RES:	[x]		Tyre:	OK	/	Rim:			,	Hubcap:	
Wheel RR:	[x]	DUNLOP	Tyre:	OK	[x] 2-4/	Rim:			,	Hubcap:	
Wheel FR:	[x]	DUNLOP	Tyre: $[x]$	OK	[x] 2-4/	Rim:	[x]	WHEEL SCRATCHED	,	Hubcap:	
Wheel RL:	[x]	DUNLOP	Tyre:	OK	[x] 2-4/	Rim:			,	Hubcap:	
Wheel FL:	[x]	DUNLOP	Tyre:	OK	[x] 2-4/	Rim:			/	Hubcap:	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	Н
Rear tyre	205	55	R	16	Н

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/	Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/	Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/	Hubcap:
	•					•
Wheel RR:	Tyre:	OK	/	Rim:	/	Hubcap:
	-3					
Wheel RES:	Tyre:	OK	/	Rim:	/	Hubcap:
White RES.	1,110.	OIL	,	Tum •	,	Hubtup .

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 31/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

[x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

В	OC	ly	W	or	k	\&	wi	nd	low:	S
---	----	----	---	----	---	----	----	----	------	---

REAR MUDGUARD/RIGHT/CENTER OTHER DAMAGES SLECHTE HERSTELLING

Number Code Description Unit price Depr. Total

0 0

[x]

[X] ROOF /FRONT/LEFT/CENTER OTHER DAMAGES SLECHTE HERSTELLING

Number Code Description Unit price Depr. Total

0 0

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
0	0	0	0
NA Deprec. 0		BG: 0	HOG: 0
0.00%			

TOTAL



31/10/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No	0							
CIRCUMS	STANCES		NORMAL CONCLUSION					
Extra Time :	0 min	Waiting time : Reason :	0 min		Towing time : Reason :	0 min		
NOT EXECUTED Reason :	: No	I						
Remark :								
Prices in EUR	without VAT							
Authorized by customer :			Exec	uted by VAB Fleet So	ervices			
Remark authorized	l customer :							
Date :	31/10/2017	Hour: 14:20)					
Company : Executed by VAB I Services	Fleet							
E-Mail:	@							
Signature authorized	l by customer		<u></u>					