

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|----------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 172854 KM |
| File nr. : | 1453679 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1EJR659 / YV1BW31A1D1265204 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 01/01/2013 |
| VFS-nr. : | | Color : | BEIGE |
| Make + Model : | VOLVO / V70 | Fuel type : | DIESEL |
| Object nr. : | 12144 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | DURACELL SOLUTIONS BVBA | Co2: | 119g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | TISSUE | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | V70 D3 Kinetic St/St 136PK | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|---------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | |
| Variant car: | BREAK | Engine size: | 1984 |
| Gear box : | Manueel | Number of places: | 5 |
| Number of gears: | 6 | Number of doors: | 5 |
| HP: | 136 | kW: | 100 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |
| General condition: | | | |

| | | | | |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | |
| Fuel card : | | | Car radio : | |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | | | Oil level : | OK [x] |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | |
|------------|-----|----------|--------|-----|-----|------|-------|-------|--------------------------------|
| Wheel FL: | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RL : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel FR : | [x] | MICHELIN | Tyre : | [x] | OK | [x] | 2-4/ | Rim : | [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RR : | [x] | MICHELIN | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RES: | [x] | | Tyre : | OK | / | | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225 | 55 | R | 16 | W |
| Rear tyre | 225 | 55 | R | 16 | W |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/LEFT/CENTER DENT
- [x] FRONT MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | | | | | |
|-----|---------------------------|---------------|-----------------------------|--------------------------|----------------------|--|--------------|--|--------------|
| [x] | REAR BUMPER/CENTER/LEFT | | SCRATCH WITH PAINT DAMAGE | | | | | | |
| | | | | Repair paint - LI | New paint - E | | Depr. | | Total |
| 4 | 0 LU =0.00 EUR | | | 254.16 EUR | | | 50 % | | 254.16 EUR |
| [x] | REAR THRESHOLD/LEFT/REAR | | DENT | | | | | | |
| | Number | Code | Description | | Unit price | | Depr. | | Total |
| 2 | I 1 | i-vab-sp-01 | SPOTREPAIR | | 115.56 EUR | | | | 115.56 EUR |
| [x] | REAR THRESHOLD/RIGHT/REAR | | DENT | | | | | | |
| | Number | Code | Description | | Unit price | | Depr. | | Total |
| 1 | I 1 | i-vab-sp-01 | SPOTREPAIR | | 115.56 EUR | | | | 115.56 EUR |
| [x] | REAR DOOR/RIGHT/FRONT | | DENT | | | | X6 | | |
| | Number | Code | Description | | Unit price | | Depr. | | Total |
| 5 | I 1 | i-vab-uitd-03 | BEAT OUT DENT (HAIL DAMAGE) | | 97.80 EUR | | | | 97.80 EUR |
| [x] | FRONT DOOR/RIGHT/FRONT | | DENT | | | | | | |
| | | | | Repair paint - LI | New paint - E | | Depr. | | Total |
| 6 | 10 LU =48.00 EUR | | | 382.02 EUR | | | 50 % | | 430.02 EUR |
| [x] | FRONT BUMPER/RIGHT/SIDE | | SCRATCH WITH PAINT DAMAGE | | | | | | |
| | | | | Repair paint - LI | New paint - E | | Depr. | | Total |
| 3 | 0 LU =0.00 EUR | | | 254.16 EUR | | | 50 % | | 254.16 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|--------|--------|--------|--------|-------|--------|---|---|---|----|
| 115.56 | 115.56 | 254.16 | 254.16 | 97.80 | 430.02 | 0 | 0 | 0 | 0 |
| 115.56 | 115.56 | 127.08 | 127.08 | 97.80 | 215.01 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 328.92 | 938.34 | 0 | 1267.26 |
| HOG: 0 | BG: 2 | | NA Deprec. 798.09 |
| | | | 0.00% |
| | | | TOTAL 798.09 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 30/10/2017 Hour : 14:01 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |