

www.vabfleetservices.be Date: 06/11/2017 1/5

D7HPA6

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 199069 KM File nr. : Mileage start / arrival: 0 / 01454772 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1EWZ811 / WBA3D91090F405188 / E-File nr. : First registration: 11/04/2013 VFS-nr.: Color: **BLACK** Make + Model : Fuel type : BMW / 3 **DIESEL** Object nr. : Fuel: 37065 **Environment Class:** Classification: EURO 5 Customer company: Co2: SECURITAS TRANSPORT 118g/km AVIATION SECURITY NV Driver: Remote controls: Covering: LEATHER Number keys: 1 [x] Vehicle kind: VEHICLE Seats (minivan): Vehicle type: 3 BER 316d 116PK Country registration: **BELGIUM**

Variant car:	BERLINE	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:		<u> </u>	

Metallic paint:

Yes



Jack, wheelspanner :

APPRAISAL

www.vabfleetservices.be Date: 06/11/2017 2/5

Original registr. number : OK Service manual : Cert. of conformity: Cert. of reg. / Part 1: OK Cert. of reg. copy / Part 2: Insurance certificate: OK [x]Transport licence: Warning vest: Tax certificate: Navigation CD/SD/DVD Fuel card : Car radio: OK [x] Extinguisher: Mobile phone kit : OK [x] Warning triangle: OK [x] Oil level: First aid kit : OK OK [x] [x]

Filled up:

0

Wheels and tyres: Summer tires

Wheel F	EL:	[x]	DUNLOP	Tyre:	O	K	[x]	2-4 /	Rim:		/ Hubcap:	
Wheel R	RL:	[x]	DUNLOP	Tyre:	O	K	[x]	2-4 /	Rim:		/ Hubcap:	
Wheel F	R:	[x]	DUNLOP	Tyre:	x] O	K	[x]	2-4 /	Rim:		/ Hubcap:	
Wheel R	RR:	[x]	DUNLOP	Tyre:	O	K	[x]	2-4 /	Rim:		/ Hubcap:	
Wheel R	RES:	[x]		Tyre:	O	K		/	Rim:		/ Hubcap:	
			[x]	Width			Hei	ight		Туре	Rim	Index
	Front	tyre		205			5	50		R	17	W
	Rear	tyre		205			5	50		R	17	W

Remark:

Wheels and tyres:

	· ·				
Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



06/11/2017 Date: www.vabfleetservices.be 3/5

STATUS: ACCEPTABLE / USAGE DAMAGE

Bo	dywork \& windows				
[x]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE		
x]	REAR DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		
x]	REAR DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE		
κ]	FRONT DOOR/LEFT/CENTER		DENT		
x]	FRONT MUDGUARD/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE		
ST	ATUS: NOT ACCEPTA	BLE			
Во	dywork \& windows				
,	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE		
[x]	REAR BOWN ENCENTER/LEFT		SERVICE WITH TARVE DAWN GE		
хj	REAR BUMI ENCENTENCE I	Repair paint - LI	New paint - E	Depr.	Total
	5 0 LU =0.00 EUR	Repair paint - LI 211.80 EUR		Depr. 50 %	Total 211.80 EUF
				-	
	5 0 LU =0.00 EUR		New paint - E	50 %	
	5 0 LU =0.00 EUR	211.80 EUR	New paint - E OTHER DAMAGES	50 % INWERKING	211.80 EUF
x]	5 0 LU =0.00 EUR ROOF/CENTER/LEFT	211.80 EUR Repair paint - LI	New paint - E OTHER DAMAGES	50 % INWERKING Depr.	211.80 EUF
x]	5 0 LU =0.00 EUR ROOF/CENTER/LEFT 2 0 LU =0.00 EUR	211.80 EUR Repair paint - LI	New paint - E OTHER DAMAGES New paint - E	50 % INWERKING Depr.	211.80 EUF
x]	5 0 LU =0.00 EUR ROOF/CENTER/LEFT 2 0 LU =0.00 EUR FRONT THRESHOLD/LEFT/REAR	211.80 EUR Repair paint - LI 481.50 EUR	New paint - E OTHER DAMAGES New paint - E OTHER DAMAGES	50 % INWERKING Depr. 50 %	211.80 EUF Total 481.50 EUF
x] x]	5 0 LU =0.00 EUR ROOF/CENTER/LEFT 2 0 LU =0.00 EUR FRONT THRESHOLD/LEFT/REAR Number Code	211.80 EUR Repair paint - LI 481.50 EUR Description	New paint - E OTHER DAMAGES New paint - E OTHER DAMAGES Unit price	50 % INWERKING Depr. 50 %	211.80 EUF Total 481.50 EUF
-	5 0 LU =0.00 EUR ROOF/CENTER/LEFT 2 0 LU =0.00 EUR FRONT THRESHOLD/LEFT/REAR Number Code 4 I 1 i-vab-ander-01	211.80 EUR Repair paint - LI 481.50 EUR Description	New paint - E OTHER DAMAGES New paint - E OTHER DAMAGES Unit price 18.74 EUR	50 % INWERKING Depr. 50 %	211.80 EUF Total 481.50 EUF

OUTSIDE MIRROR LEFTHAND SIDE		BROKEN / CRACKED				
	Repair paint - LI	New paint - E	Depr.	Total		
3 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR		

	אן	ieces	
--	----	-------	--

[x]

1	Number	Code	Description	Unit price	Depr.	Totai
3	1	MIRROR COVER		120.00 EUR	50 %	120.00 EUR



www.vabfleetservices.be Date: 06/11/2017 4/5

1	2	3	4	5	6	7	8	9	10
211.80	481.50	144.00	18.74	211.80	0	0	0	0	0
105.90	240.75	72.00	18.74	105.90	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
18.74	1049.10	0		1067.84
HOG: 0	BG: 0		NA Deprec.	543.29
			0.00%	
			TOTAL	543.29



www.vabfleetservices.be Date: 06/11/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMS	TANCES		UNDER CONDITION - DUSTY VEHICLE				
Extra Time :	0 min	Waiting time: 0 m	nin	Towing time :	0 min		
		Reason :		Reason:			
NOT EXECUTED :	No						
Reason:							
Remark :							
Prices in EUR v	vithout VAT						
Authorized by customer :			Executed by VAB	Fleet Services			
Remark authorized	customer :						
Date :	06/11/2017	Hour: 13:48					
Company :							
Executed by VAB F. Services	leet						
E-Mail :	@						
Signature authorized	by customer						