

D8E7HH

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	149805 KM
File nr. :	1455439	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GHX519 / WBA3Y110X0D375961 /		yr of constructionr :	/
E-File nr. :		First registration :	12/02/2014
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 3 GT	Fuel type :	DIESEL
Object nr. :	33860	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	AVNET EUROPE CVA//EM	Co2:	127g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x] PIRELLI	Tyre :	OK [x] 2-4/	Rim :	[x] WHEEL SCRATCHED	/ Hubcap :	
Wheel RL :	[x] PIRELLI	Tyre :	OK [x] 2-4/	Rim :		/ Hubcap :	
Wheel FR :	[x] PIRELLI	Tyre :	[x] OK [x] 2-4/	Rim :		/ Hubcap :	
Wheel RR :	[x] PIRELLI	Tyre :	OK [x] 2-4/	Rim :		/ Hubcap :	
Wheel RES:	[x]	Tyre :	OK /	Rim :		/ Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	18	W
Rear tyre	225	50	R	18	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel RL :		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel FR :		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel RR :		Tyre :	OK /	Rim :		/ Hubcap :	
Wheel RES:		Tyre :	OK /	Rim :		/ Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR BUMPER/LEFT/LEFT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE
- [x] REAR BUMPER/CENTER/RIGHT SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

		OTHER DAMAGES	INWERKING	
	Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	577.80 EUR	50 %	577.80 EUR

1	2	3	4	5	6	7	8	9	10
577.80	0	0	0	0	0	0	0	0	0
288.90	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	577.80	0	577.80
HOG: 0	BG: 2		NA Deprec. 288.90
			0.00%
			TOTAL 288.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : 14:22 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	