

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	150025 KM
File nr. :	1456195	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FV1412 / WBA3D11050J625264 /		yr of constructionr :	/
E-File nr. :		First registration :	06/11/2013
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :	702806	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CEGELEC REFRIGERATION	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 BER 318d 143PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	143	kW:	105
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	[x]
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	DUNLOP	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	DUNLOP	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	DUNLOP	Tyre :	[x] OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	DUNLOP	Tyre :	OK [x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	[x]	BRIDGESTONE	Tyre :	OK	/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Interior

- [x] DOOR IN FL CARVED
- [x] DOOR IN FR CARVED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		DENT						
		Repair paint - LI	New paint - E		Depr.		Total		
2	0 LU =0.00 EUR	211.80 EUR			50 %		211.80 EUR		
[x]	REAR DOOR/RIGHT/FRONT		DENT						
		Repair paint - LI	New paint - E		Depr.		Total		
3	30 LU =144.00 EUR	0 EUR	435.72 EUR		50 %		579.72 EUR		
[x]	FRONT DOOR/RIGHT/REAR		DENT						
		Repair paint - LI	New paint - E		Depr.		Total		
3	30 LU =144.00 EUR	0 EUR	435.72 EUR		50 %		579.72 EUR		
[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAINT DAMAGE						
		Repair paint - LI	New paint - E		Depr.		Total		
1	0 LU =0.00 EUR	211.80 EUR			50 %		211.80 EUR		

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	DOOR REAR RIGHT	367.20 EUR	50 %	367.20 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	DOOR FR	502.80 EUR	50 %	502.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	211.80	2029.44	0	0	0	0	0	0	0
105.90	105.90	1014.72	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	2453.04	0	2453.04
HOG: 0	BG: 0		NA Deprec. 1226.52
			0.00%
			TOTAL 1226.52

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/11/2017 Hour : 10:40 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	