

www.vabfleetservices.be Date: 03/11/2017 1/4

D77NCT

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

No

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	126016 KM
File nr. :	1454550	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DOB993 / WBA1C910X0J	199466 /	yr of constructionr :	2012 / 07
E-File nr. :		First registration :	05/07/2012
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 1	Fuel type :	DIESEL
Object nr. :		Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	KBC AUTOLEASE NV/SA	Co2:	88g/km
Driver :		Remote controls:	2
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan):	0
Vehicle type :	1 HATCH 116d Eff.Dyn.Ed. 116PK	Country registration :	BELGIUM

Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	3
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		l	

Metallic paint:

Yes



www.vabfleetservices.be Date: 03/11/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

		[v]	Width		He	ight		Tyne		Rim	Index	
Wheel RES:	[x]		Tyre:	OK		/	Rim:		/	Hubcap:		
Wheel RR:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:		/	Hubcap:		
Wheel FR:	[x]	MICHELIN	Tyre: [x] OK	[x]	2-4 /	Rim:		/	Hubcap:		
Wheel RL:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:		/	Hubcap:		
Wheel FL:	[x]	MICHELIN	Tyre:	OK	[x]	2-4 /	Rim:		/	Hubcap:		

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	205	55	R	16	W
	Rear tyre	205	55	R	16	W

Remark: REPARATIEKIT AANWEZIG

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 03/11/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

[x] REAR LIGHT/LEFT/CORNER SCRATCH WITH PAINT DAMAGE

[x] REAR DOOR/LEFT/CENTER DENT

[x] FRONT DOOR/LEFT/FRONT DENT

[x] FRONT BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] FRONT BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

Bodywork \& windows

[x] REAR DOOR/LEFT/FRONT DENT

]	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	-	63.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	0	0	0	0	0	0	0	0	0
63.00	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
63.00	0	0	63.00
NA Deprec. 63.00		BG: 0	HOG: 0
0.00%			

TOTAL

63.00



www.vabfleetservices.be Date: 03/11/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUM	STANCES		NORMAL CONCL	USION	
Extra Time :	0 min	Waiting time: 0 mir Reason:	1	Towing time : Reason :	0 min
NOT EXECUTED Reason:	D: No				
Remark :					
Prices in EUR	R without VAT				
Authorized by customer :			Executed by VAB Fleet S	Gervices	
Remark authoriz	ed customer :				
Date :	03/11/2017	Hour: 09:32			
Company : Executed by VAB Services	3 Fleet				
E-Mail :	@				
Signature authorize	ed by customer		†		