

www.vabfleetservices.be Date: 06/11/2017 1/5

D8F2IX

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	160270 KM
File nr. :	1455467	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CCS250 / WBAUY71060)A989902 /	yr of constructionr :	/
E-File nr. :		First registration :	20/10/2011
VFS-nr. :		Color :	SILVER
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :	12055	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company:	ERICSSON N.V./S.A.	Со2:	114g/km
Driver :		Remote controls:	2
Covering:	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	3 TOURING 320d Eff.Dynamics Ed. 163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	163	kW:	120
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		1	



www.vabfleetservices.be Date: 06/11/2017 2/5

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :			Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Front tyre	[x]	Width 205			ight			Type R		Rim 16	Index V
	[x]	Width		Hei	ight			Туре		Rim	Index
Wheel RES: [x]		Tyre:	OK		/	Rim:				/ Hubcap:	
Wheel RR: [x]	MICHE	ELIN Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FR: [x]	MICHE	ELIN Tyre: [x] OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel RL: [x]	MICHE	ELIN Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel FL: [x]	MICHE	ELIN Tyre:	ОК	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

 [x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:

Remark:



1 0 LU =0.00 EUR

2 0 LU =0.00 EUR

[x]

FRONT BUMPER/CENTER/RIGHT

APPRAISAL

Date: 06/11/2017 www.vabfleetservices.be 3/5

_	STATUS: ACCEPTABLE / USAGE DAMAGE								
Во	dywork \& windows								
[x]	REAR DOOR/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE						
[x]	REAR MUDGUARD/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE						
[x]	REAR DOOR/RIGHT/FRONT		DENT						
[x]	FRONT THRESHOLD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE						
Int	erior								
[x]	SEAT REAR L		STAIN						
Ac	cessories and others								
[x]	ROOF RAILS		OTHER DAMAGES						
ST	ATUS: NOT ACCEPTABL	E							
Во	dywork \& windows								
[x]									
	REAR BUMPER/CENTER/LEFT		DENT						
	REAR BUMPER/CENTER/LEFT	Repair paint - LI	DENT New paint - E	Depr.	Total				
	REAR BUMPER/CENTER/LEFT 4 0 LU =0.00 EUR	Repair paint - LI 211.80 EUR		Depr. 50 %	Total 211.80 EUR				
[x]									
[x]	4 0 LU =0.00 EUR		New paint - E						
[x]	4 0 LU =0.00 EUR REAR WINDOW STYLE/CENTER/LEFT/UP	211.80 EUR	New paint - E SCRATCH WITH PAINT DAMAGE	50 %	211.80 EUR				
[x]	4 0 LU =0.00 EUR REAR WINDOW STYLE/CENTER/LEFT/UP Number Code 5 I 1 i-vab-sp-01	211.80 EUR Description	New paint - E SCRATCH WITH PAINT DAMAGE Unit price	50 %	211.80 EUR Total				
	4 0 LU =0.00 EUR REAR WINDOW STYLE/CENTER/LEFT/UP Number Code 5 I 1 i-vab-sp-01	211.80 EUR Description	New paint - E SCRATCH WITH PAINT DAMAGE Unit price 115.56 EUR	50 %	211.80 EUR Total				
	4 0 LU =0.00 EUR REAR WINDOW STYLE/CENTER/LEFT/UP Number Code 5 I 1 i-vab-sp-01	211.80 EUR Description SPOTREPAIR	New paint - E SCRATCH WITH PAINT DAMAGE Unit price 115.56 EUR SCRATCH WITH PAINT DAMAGE	50 % Depr.	211.80 EUR Total 115.56 EUR				
	4 0 LU =0.00 EUR REAR WINDOW STYLE/CENTER/LEFT/UP Number Code 5 I 1 i-vab-sp-01 THRESHOLD FRONT/LEFT/CENTER	211.80 EUR Description SPOTREPAIR Repair paint - LI	New paint - E SCRATCH WITH PAINT DAMAGE Unit price 115.56 EUR SCRATCH WITH PAINT DAMAGE	Depr. Depr.	211.80 EUR Total 115.56 EUR Total				

290.08 EUR

Repair paint - LI

211.80 EUR

290.08 EUR

Total

211.80 EUR

50 %

Depr.

50 %

SCRATCH WITH PAINT DAMAGE

New paint - E



www.vabfleetservices.be Date: 06/11/2017 4/5

1	2	3	4	5	6	7	8	9	10
290.08	211.80	310.50	211.80	115.56	0	0	0	0	0
145.04	105.90	155.25	105.90	115.56	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
1139.74		0	1024.18	115.56
627.65	NA Deprec.		BG: 0	HOG: 0
	0.00%			
627.65	TOTAL			



www.vabfleetservices.be Date: 06/11/2017 5/5

[x] = Status Modification

Pictures: No

CIRCUMS	TANCES		NORMAL CONCLUSION			
Extra Time :	0 min	Waiting time: 0 min Reason:	1	Towing time : Reason :	0 min	
NOT EXECUTED Reason:	: No	<u> </u>		1		
Remark :						
Prices in EUR	without VAT					
Authorized by customer :			Executed by VAB Fleet	Services		
Remark authorized	l customer :					
Date : Company :	06/11/2017	Hour: 16:18				
Executed by VAB F Services	Fleet					
E-Mail :	@					
Signature authorized	l by customer	-				