

D7GR2V

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	80443 KM
File nr. :	1454753	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FQT177 / WBA3K11090F855270 /		yr of constructionr :	/
E-File nr. :		First registration :	26/09/2013
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :	176	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SOLVAY SA	Co2:	123g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 TOURING 318dA 136PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	[x]
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	[x]	Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	CONTINENTAL	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel RL :	CONTINENTAL	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel FR :	CONTINENTAL	Tyre :	OK	4-6/	Rim :	WHEEL SCRATCHED	Hubcap :
Wheel RR :	CONTINENTAL	Tyre :	OK	4-6/	Rim :	WHEEL SCRATCHED	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	W
Rear tyre	205	60	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/FRONT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT DENT

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	0 EUR		50 %	
4 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] ROOF/CENTER/RIGHT OTHER DAMAGES CHEMISCHE INWERKING

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR

[x] FRONT DOOR/LEFT/REAR DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

[x] BONNET/CENTER/RIGHT OTHER DAMAGES CHEMISCHE INWERKING

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1 REFLECTOR		15.00 EUR	50 %	15.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	318.35	771.58	226.80	190.00	0	0	0	0	0
105.90	159.18	385.79	113.40	190.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
190.00	1528.53	0	1718.53
HOG: 0	BG: 0		NA Deprec. 954.26
			0.00%
			TOTAL 954.26

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : 15:41 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	