

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	134141 KM
<b>File nr. :</b>	1453810	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1AVY721 / ZCFC35A3805860214 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	04/04/2011
<b>VFS-nr. :</b>		<b>Color :</b>	BLUE
<b>Make + Model :</b>	IVECO / DAILY	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	46115	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 4
<b>Customer company :</b>	GEMEENTE ETTERBEEK	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	IMITATION LEATHER	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	TRUCK, LORRY	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	DAILY 35C B/F MWB 35C15V 146PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	2998
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	3
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	146	<b>kW:</b>	107
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL: [x] BRIDGESTONE Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RL : [x] BRIDGESTONE Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel FR : [x] BRIDGESTONE Tyre : [x] OK [x] 4-6/ Rim : / Hubcap :
Wheel RR : [x] BRIDGESTONE Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	16	
Rear tyre	195	65	R	16	

Remark :

## Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	FRONT DOOR/RIGHT/REAR	DENT
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	DENT	BINNEN
		<b>Repair paint - LI</b>	<b>New paint - E</b>
		<b>Depr.</b>	<b>Total</b>
7	0 LU =0.00 EUR	0 EUR	50 %
		<b>Repair paint - LI</b>	<b>New paint - E</b>
		<b>Depr.</b>	<b>Total</b>
7	20 LU =96.00 EUR	0 EUR	366.49 EUR
		50 %	462.49 EUR
[x]	REAR DOOR/CENTER/RIGHT	DENT	BINNEN
		<b>Repair paint - LI</b>	<b>New paint - E</b>
		<b>Depr.</b>	<b>Total</b>
7	0 LU =0.00 EUR	0 EUR	50 %
		<b>Repair paint - LI</b>	<b>New paint - E</b>
		<b>Depr.</b>	<b>Total</b>
7	20 LU =96.00 EUR	0 EUR	366.49 EUR
		50 %	462.49 EUR
[x]	REAR MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	+DEUK
		<b>Repair paint - LI</b>	<b>New paint - E</b>
		<b>Depr.</b>	<b>Total</b>
4	0 LU =0.00 EUR	231.15 EUR	50 %
			231.15 EUR
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
		<b>Repair paint - LI</b>	<b>New paint - E</b>
		<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR	238.76 EUR	50 %
			238.76 EUR
[x]	REAR DOOR/RIGHT/FRONT	DENT	
		<b>Repair paint - LI</b>	<b>New paint - E</b>
		<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR	238.76 EUR	50 %
			238.76 EUR
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
		<b>Repair paint - LI</b>	<b>New paint - E</b>
		<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR	238.76 EUR	50 %
			238.76 EUR

[x]	ROOF STYLE/FRONT/LEFT/CENTER		DENT		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	0 LU =0.00 EUR	165.14 EUR		50 %	165.14 EUR

[x]	FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
8	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

### Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE		OTHER DAMAGES		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
6	0 LU =0.00 EUR	0 EUR		50 %	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
6	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
6	1	LICHT	60.00 EUR	50 %	60.00 EUR
Number	Code	Description	Unit price	Depr.	Total
7	1	TRUNK	337.50 EUR	50 %	337.50 EUR
Number	Code	Description	Unit price	Depr.	Total
7	1	TRUNK	337.50 EUR	50 %	337.50 EUR

1	2	3	4	5	6	7	8	9	10
165.14	238.76	238.76	231.15	238.76	84.00	1599.98	110.64	0	0
82.57	119.38	119.38	115.58	119.38	42.00	799.99	110.64	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
110.64	2796.55	0	<b>2907.19</b>
HOG: 0	BG: 3		NA Deprec. 1508.92
			0.00%
			<b>TOTAL 1508.92</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 08/11/2017 <b>Hour :</b> <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b> 	