

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	70198 KM
File nr. :	1453811	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1BAW053 / WFOXXXTTFXBD72389 /		yr of constructionr :	/
E-File nr. :		First registration :	20/04/2011
VFS-nr. :		Color :	BLUE
Make + Model :	FORD / TRANSIT	Fuel type :	DIESEL
Object nr. :	46115	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	GEMEENTE ETTERBEEK	Co2:	222g/km
Driver :		Remote controls:	1
Covering :	IMITATION LEATHER	Number keys :	3 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	TRANSIT B/F 280M MWB Ambiente DPF 85PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	2198
Gear box :	Manueel	Number of places:	3
Number of gears:	5	Number of doors:	5
HP:	86	kW:	63
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	[x] MISSING/INCOMPLETE
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	70	R	15	
Rear tyre	195	70	R	15	

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR DOOR/CENTER/LEFT DENT
- [x] REAR DOOR/CENTER/RIGHT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
	5 0 LU =0.00 EUR		231.15 EUR		50 %
					Total
					231.15 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			+DEUK
			Repair paint - LI	New paint - E	Depr.
	6 0 LU =0.00 EUR		231.15 EUR		50 %
					Total
					231.15 EUR
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			+DEUK
			Repair paint - LI	New paint - E	Depr.
	4 0 LU =0.00 EUR		238.76 EUR		50 %
					Total
					238.76 EUR
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
	6 0 LU =0.00 EUR		238.76 EUR		50 %
					Total
					238.76 EUR
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
			Number	Code	Description
	0	0			Unit price
					Depr.
					Total
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
			Number	Code	Description
	0	0			Unit price
					Depr.
					Total
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			+DEUKEN
			Repair paint - LI	New paint - E	Depr.
	3 0 LU =0.00 EUR		238.76 EUR		50 %
					Total
					238.76 EUR
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			+DEUK
			Repair paint - LI	New paint - E	Depr.
	7 0 LU =0.00 EUR		238.76 EUR		50 %
					Total
					238.76 EUR

[x]	FRONT MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	+DEUK		
		Repair paint - LI	New paint - E	Depr.	Total
8	0 LU =0.00 EUR	165.13 EUR		50 %	165.13 EUR

Interior

[x]	SEAT FR	HOLE			
		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
10	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	BROKEN / CRACKED			
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
9	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

	HUB CAP REAR L				
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
9	1	MIRROR COVER	90.00 EUR	50 %	90.00 EUR
10	1	ZETELBEKLEDING NAMAAKLEDER	135.00 EUR	50 %	135.00 EUR

1	2	3	4	5	6	7	8	9	10
0	22.50	238.76	238.76	231.15	469.91	238.76	165.13	114.00	255.00
0	11.25	119.38	119.38	115.58	234.96	119.38	82.56	57.00	127.50

INNOVATIVE	TRADITIONAL	GENERAL	
0	1973.97	0	1973.97
HOG: 0	BG: 3		NA Deprec. 986.98
			0.00%
			TOTAL 986.98

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	