

D4VYYH

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	118569 KM
File nr. :	1452647	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
LH1188 / WDF63981513756641 /		yr of constructionr :	/
E-File nr. :		First registration :	29/01/1918
VFS-nr. :		Color :	SILVER
Make + Model :	MERCEDES / VIANO	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	BANK OF CHINA (LUXEMBOURG) SA	Co2:	g/km
Driver :		Remote controls:	3
Covering :	LEATHER	Number keys :	3 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	VIANO LWB Ambiente 224PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	
Gear box :	Automaat algemeen	Number of places:	8
Number of gears:		Number of doors:	5
HP:		kW:	
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : [x]
Cert. of reg. / Part 1: [x]	Cert. of conformity :
Cert. of reg. copy / Part 2: [x]	Insurance certificate : OK
Warning vest : [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK
Mobile phone kit : [x]	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner : [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL: [x] MICHELIN	Tyre : OK [x] 2-4/	Rim : [x] WHEEL SCRATCHED	Hubcap : MISSING/INCOMPLETE
Wheel RL : [x] MICHELIN	Tyre : OK [x] 2-4/	Rim : [x] WHEEL SCRATCHED	Hubcap : MISSING/INCOMPLETE
Wheel FR : [x] MICHELIN	Tyre : [x] OK [x] 2-4/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel RR : [x] MICHELIN	Tyre : OK [x] 2-4/	Rim : [x] WHEEL SCRATCHED	Hubcap :
Wheel RES: [x]	Tyre : OK [x] /	Rim :	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	M+S
Rear tyre	225	55	R	17	M+S

Remark :

Wheels and tyres:

Wheel FL:	Tyre : OK /	Rim :	Hubcap :
Wheel RL :	Tyre : OK /	Rim :	Hubcap :
Wheel FR :	Tyre : OK /	Rim :	Hubcap :
Wheel RR :	Tyre : OK /	Rim :	Hubcap :
Wheel RES:	Tyre : OK /	Rim :	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	FRONT DOOR/RIGHT/REAR	DENT	3X
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
6	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR
[x]	REAR MUDGUARD/LEFT/FRONT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	369.84 EUR		50 %	369.84 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER	OTHER DAMAGES		SLECHT HERSTELD	
	Number Code	Description	Unit price	Depr.	Total
0	0				
[x]	REAR DOOR/LEFT/REAR	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
5	0 LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR
[x]	ROOF/REAR/LEFT	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
10	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR
[x]	ROOF/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
7	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR
[x]	FRONT MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	264.21 EUR		50 %	264.21 EUR

[x] FRONT MUDGUARD/RIGHT/REAR		OTHER DAMAGES		SL HERSTELD	
Number	Code	Description	Unit price	Depr.	Total
0	0				
[x] FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	10 LU =48.00 EUR	254.16 EUR		50 %	302.16 EUR

Interior

LUGGAGE COVER		MISSING/INCOMPLETE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	

Accessories and others

[x] OUTSIDE MIRROR LEFTHAND SIDE		BROKEN / CRACKED			
		Repair paint - LI	New paint - E	Depr.	Total
3	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR
[x] OUTSIDE MIRROR RIGHTHAND SIDE		SCRATCH WITH PAINT DAMAGE			
Number	Code	Description	Unit price	Depr.	Total
9	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

Others

RIM REAR LEFT					
Number	Code	Description	Unit price	Depr.	Total
8	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR
RIM REAR RIGHT					
Number	Code	Description	Unit price	Depr.	Total
8	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR
RIM FRONT RIGHT					
Number	Code	Description	Unit price	Depr.	Total
8	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	LUGGAGE COVER	288.00 EUR	50 %	288.00 EUR
Number	Code	Description	Unit price	Depr.	Total
3	1	MIRROR	144.00 EUR	50 %	144.00 EUR
Number	Code	Description	Unit price	Depr.	Total
7	1	SCHUIFDAK	500.00 EUR	50 %	500.00 EUR
Number	Code	Description	Unit price	Depr.	Total
10	1	VOET	35.00 EUR	50 %	35.00 EUR

1	2	3	4	5	6	7	8	9	10
288.00	566.37	192.00	382.02	751.86	254.16	620.00	285.00	115.56	59.00
144.00	283.18	96.00	191.01	375.93	127.08	310.00	285.00	115.56	29.50

INNOVATIVE	TRADITIONAL	GENERAL	
400.56	3113.41	0	3513.97
HOG: 0	BG: 2		NA Deprec. 1957.26
			0.00%
			TOTAL 1957.26

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : 11:42 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	