

D9OWAN

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	180208 KM
File nr. :	1456467	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CHW865 / WOLF7B0B6CV606354 /		yr of constructionr :	/
E-File nr. :		First registration :	01/12/2011
VFS-nr. :		Color :	WHITE
Make + Model :	OPEL / VIVARO	Fuel type :	DIESEL
Object nr. :	72417	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CEGELEC BUILDING SERVICES	Co2:	198g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	VIVARO 2900 B/F MWB L2H1 DPF(EU5) 90PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	1995
Gear box :	Manueel	Number of places:	3
Number of gears:	6	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	NOK [x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	[x]
Fuel card :		Car radio :	[x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	FULDA	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	FULDA	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	FULDA	Tyre :	[x] OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	FULDA	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	65	R	16	R
Rear tyre	215	65	R	16	R

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE
- [x] FRONT THRESHOLD/LEFT/FRONT DENT

Accessories and others

- [x] VEH COVERED WITH STICKERS STICKER(S)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

Number	Code	Description	Unit price	Depr.	Total
[x]		REAR MUDGUARDL/CENTER/RIGHT		DENT	
6	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]		REAR DOOR/RIGHT/FRONT		OTHER DAMAGES	ROEST
				Repair paint - LI	New paint - E
5	0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR
[x]		ROOF STYLE/FRONT/LEFT/CENTER		DENT	
				Repair paint - LI	New paint - E
7	0 LU =0.00 EUR	165.14 EUR		50 %	165.14 EUR
[x]		FRONT THRESHOLD/RIGHT/REAR		DENT	
				Repair paint - LI	New paint - E
3	25 LU =120.00 EUR	232.88 EUR		50 %	352.88 EUR
[x]		FRONT MUDGUARD/RIGHT/REAR		DENT	
				Repair paint - LI	New paint - E
4	0 LU =0.00 EUR	165.13 EUR		50 %	165.13 EUR
[x]		FRONT BUMPER/RIGHT		DENT	
				Repair paint - LI	New paint - E
2	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

Interior

[x]		BOOT LID IN		MISSING/INCOMPLETE	
				Repair paint - LI	New paint - E
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	BEKLEDING	25.00 EUR	50 %	25.00 EUR

1	2	3	4	5	6	7	8	9	10
49.00	110.64	352.88	165.13	238.76	63.00	165.14	0	0	0
24.50	110.64	176.44	82.56	119.38	63.00	82.57	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
173.64	970.91	0	1144.55
HOG: 0	BG: 3		NA Deprec. 659.10
			0.00%
			TOTAL 659.10

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/11/2017 Hour : 15:46 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	