

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	86779 KM
File nr. :	1454312	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FMA491 / VF1KZ140649457540 /		yr of constructionr :	/
E-File nr. :		First registration :	13/08/2013
VFS-nr. :		Color :	BLACK
Make + Model :	RENAULT / MEGANE	Fuel type :	DIESEL
Object nr. :	47067	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Atos Belgium NV	Co2:	90g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	MEGANE GT Energy Business 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD	OK	[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	1.6-2/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	1.6-2/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	MICHELIN	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	H
Rear tyre	195	65	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	ROOF/REAR/LEFT	DENT
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
6	15 LU =72.00 EUR		0 EUR		50 %
					72.00 EUR
[x]	REAR DOOR/CENTER/RIGHT	DENT			MET LAKSCHADE
			Repair paint - LI	New paint - E	Depr.
					Total
7	0 LU =0.00 EUR		301.68 EUR		50 %
					301.68 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
8	35 LU =168.00 EUR		308.20 EUR		50 %
					476.20 EUR
[x]	REAR BUMPER/SIDE/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
	Number	Code	Description	Unit price	Depr.
					Total
8	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR	
					115.56 EUR
[x]	REAR DOOR/LEFT/REAR	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
5	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	
					63.00 EUR
[x]	REAR DOOR/RIGHT/REAR	OTHER DAMAGES			
			Repair paint - LI	New paint - E	Depr.
					Total
8	0 LU =0.00 EUR		0 EUR		50 %
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
4	25 LU =120.00 EUR		0 EUR		50 %
					120.00 EUR

[x]	FRONT BUMPER/LEFT/SIDE		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x]	BONNET/CENTER/RIGHT/FRONT		DENT			
	Number	Code	Description	Unit price	Depr.	Total
2	1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x]	FRONT/RIGHT		HOLE/CRACK/TORN		
		Repair paint - LI	New paint - E	Depr.	Total
3	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Interior

[x]	BOOT IN L		CARVED		
		Repair paint - LI	New paint - E	Depr.	Total
1	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR

Others

	HUB CAP FL				
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR			50 %	

	HUB CAP REAR L				
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR			50 %	

	HUB CAP REAR RIGHT				
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR			50 %	

	HUB CAP FR				
		Repair paint - LI	New paint - E	Depr.	Total
9	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	BEKLEDING	75.00 EUR	50 %	75.00 EUR
4	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR
6	1	REAR BUMPER	343.20 EUR	50 %	343.20 EUR
8	1	SIERLIJST	15.00 EUR	50 %	15.00 EUR
9	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
9	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
9	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
9	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
3	1	FRONT	65.00 EUR	50 %	65.00 EUR

1	2	3	4	5	6	7	8	9	10
123.00	63.00	300.80	487.20	63.00	415.20	301.68	606.76	120.00	0
61.50	63.00	150.40	243.60	63.00	207.60	150.84	361.16	60.00	0

INNOVATIVE	TRADITIONAL	GENERAL	
241.56	2239.08	0	2480.64
HOG: 0	BG: 0		NA Deprec. 1361.10
			0.00%
			TOTAL 1361.10

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : 11:22 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	