

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: DIRTY [x]
<b>Owner :</b>		<b>Mileage :</b>	97212 KM
<b>File nr. :</b>	1456623	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1GAF583 / WVWZZZ6RZEY134166 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	04/12/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	VOLKSWAGEN / POLO	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	713108	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	HANDSON & PARTNERS NV	<b>Co2:</b>	99g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	POLO Trendline DPF 75PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1199
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	75	<b>kW:</b>	55
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

## Wheels and tyres: Winter tires

Wheel FL:	BRIDGESTONE	Tyre :	OK	2-4/	Rim :	/	Hubcap :	[x] MISSING/INCOMPLETE
Wheel RL :	BRIDGESTONE	Tyre :	OK	4-6/	Rim :	/	Hubcap :	[x] MISSING/INCOMPLETE
Wheel FR :	BRIDGESTONE	Tyre :	OK	2-4/	Rim :	/	Hubcap :	[x] MISSING/INCOMPLETE
Wheel RR :	BRIDGESTONE	Tyre :	OK	4-6/	Rim :	/	Hubcap :	[x] MISSING/INCOMPLETE
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	175	70	R	14	T
Rear tyre	175	70	R	14	T

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT THRESHOLD/RIGHT/FRONT	DENT

### Accessories and others

OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH (WITHOUT PAINT DAMAGE)
-------------------------------	--------------------------------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/SIDE/LEFTCENTER	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
			<b>Total</b>		
3	0 LU =0.00 EUR		169.44 EUR		50 %
					169.44 EUR
[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
			<b>Total</b>		
4	25 LU =120.00 EUR		0 EUR		50 %
					120.00 EUR
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES			CHEMISCHE INWERKING
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
			<b>Total</b>		
2	0 LU =0.00 EUR		232.06 EUR		50 %
					232.06 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
			<b>Total</b>		
1	0 LU =0.00 EUR		169.44 EUR		50 %
					169.44 EUR

### Others

HUB CAP FL					
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
			<b>Total</b>		
5	0 LU =0.00 EUR				50 %

HUB CAP REAR L

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
4	1	BACK WINDOW	200.00 EUR	50 %	200.00 EUR
5	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
5	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
5	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
5	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

1	2	3	4	5	6	7	8	9	10
169.44	232.06	169.44	320.00	96.00	0	0	0	0	0
84.72	116.03	84.72	160.00	48.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	986.94	0	<b>986.94</b>
HOG: 0	BG: 1		NA Deprec. 493.47
			0.00%
			<b>TOTAL 493.47</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b> NAVI OK		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 08/11/2017 <b>Hour :</b> 13:56 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	