

www.vabfleetservices.be Date: 20/10/2017 1/4

D1QYDF

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	54313 KM
File nr. :	1450172	Mileage start / arrival:	0/0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HAB039 / TMBJG9NEXE02	21752 /	yr of constructionr :	/
E-File nr. :		First registration :	02/06/2014
VFS-nr. :		Color :	GREY
Make + Model :	SKODA / OCTAVIA BREAK	Fuel type :	DIESEL
Object nr. :	59676	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	VERIZON BELGIUM LUXEMBOURG NV	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
нр:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Metallic paint:

Yes



www.vabfleetservices.be Date: 20/10/2017 2/4

Original registr. number :			Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner:			Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL: Wheel RL: Wheel FR:	[x] [x] [x]	MICHE MICHE MICHE MICHE	ELIN Tyre: ELIN Tyre:	[x]	OK OK OK	[x] [x] [x]	4-6 / 4-6 / 4-6 /	Rim: Rim: Rim:	[x]	WHEEL SCRATCHED	/ Hubcap : / Hubcap : / Hubcap : / Hubcap :	
Wheel RES:	[x]		Tyre:		OK		/	Rim :	[24]		/ Hubcap:	,
		[x]	Width			He	eight			Type	Rim	Index
Fron	t tyre		225			4	45			R	17	W
Rear	tyre		225				45			R	17	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
1					

[x]	[x] Width		Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



Date: www.vabfleetservices.be 20/10/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

FRONT DOOR/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE [x]

BONNET/CENTER/RIGHT/FRONT CHIPS [x]

STATUS: NOT ACCEPTABLE

Bodvwork	\& windows
----------	-----------------------

[x] REAR MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE +DEUK

Total

Repair paint - LI New paint - E Depr.

1 0 LU =0.00 EUR 308.20 EUR 50 % 308.20 EUR

Others

RIM REAR LEFT

	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

	1	2	3	4	5	6	7	8	9	10
	308.20	190.00	0	0	0	0	0	0	0	0
ĺ	154.10	190.00	0	0	0	0	0	0	0	0

	INNOVATIVE	TRADITIONAL	GENERAL		
	190.00	308.20	0		498.20
	HOG: 0	BG: 0		NA Deprec.	344.10
٠				0.00%	

TOTAL 344.10



20/10/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No									
CIRCUMSTANCES			NORMAL CONCLUSION						
Extra Time :	0 min	Waiting ti Reason :	me: 0 min	1	Towing time : Reason :	0 min			
NOT EXECUTED : Reason :	No								
Remark :									
Prices in EUR wi	ithout VAT								
Authorized by customer :				Executed by VAB Fleet Se	rvices				
Remark authorized c	ustomer :								
Date :	20/10/2017	Hour :	07:59						
Company :									
Executed by VAB Fle Services	et								
E-Mail :	@								
Signature authorized b	y customer								
	,								