

www.vabfleetservices.be Date: 09/11/2017 1/4

D9BJW9

### [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 141159 KM File nr. : Mileage start / arrival: 0 / 01456176 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1EWK971 / YV1MV8481D2053237 / E-File nr. : First registration: 08/04/2013 Color: VFS-nr.: **BLUE D** Make + Model : Fuel type : VOLVO / V40 **DIESEL** Object nr. : Fuel: 51411 Classification: **Environment Class:** EURO 5 Customer company: Co2: CEGEKA NV 94g/kmDriver : Remote controls: 2 PARTIAL LEATHER Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: V40 D2 Base 115PK Country registration: **BELGIUM** 

VAT over the margin - car:	No	Metallic paint:	Yes				
Variant car:	BREAK	Engine size:	1560				
Gear box :	Manueel	Number of places:	5				
Number of gears:	6	Number of doors:	5				
HP:	114	kW:	84				
Fisc HP		Imported vehicle:					
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:	No				
		Use:	Unknown				
General condition:	General condition:						



www.vabfleetservices.be Date: 09/11/2017 2/4

Original registr. number : OK Service manual : OK Cert. of conformity: Cert. of reg. / Part 1: OK Insurance certificate: Cert. of reg. copy / Part 2: OK Transport licence: Warning vest: Tax certificate: Navigation CD/SD/DVD Fuel card : Car radio: OK Extinguisher: Mobile phone kit : OK Warning triangle: OK First aid kit : OK Oil level: OK Filled up: 0 Jack, wheelspanner :

#### Wheels and tyres: Summer tires

Wheel FL:	PIRELLI	Tyre:	OK	1.6-2 /	Rim:		/	Hubcap:
Wheel RL:	PIRELLI	Tyre:	OK	4-6 /	Rim:		/	Hubcap:
Wheel FR:	PIRELLI	Tyre:	OK	1.6-2 /	Rim:	WHEEL SCRATCHED	/	Hubcap:
Wheel RR:	PIRELLI	Tyre:	OK	4-6 /	Rim:		/	Hubcap:
Wheel RES:		Tyre:	OK	/	Rim:		/	Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark:

#### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 09/11/2017 3/4

#### STATUS: ACCEPTABLE / USAGE DAMAGE

#### **Bodywork \& windows**

[x] REAR MUDGUARD/RIGHT/FRONT DENT

[x] FRONT MUDGUARD/LEFT/REAR DENT

[x] FRONT BUMPER/RIGHT/SIDE SCRATCH WITH PAINT DAMAGE

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 0		NA Deprec.	0
			0.00%	
			TOTAL	0



www.vabfleetservices.be Date: 09/11/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS			NORMAL CONCLUSION						
Extra Time :	0 min	Waiting time: 0 m Reason:	in	Towing time : Reason :	0 min				
NOT EXECUTED Reason:	: No	I		l					
Remark :									
Prices in EUR	without VAT								
Authorized by customer:			Executed by VAB Fleet Se	ervices					
Remark authorized	l customer :								
Date : Company :	09/11/2017	<b>Hour:</b> 11:11							
Executed by VAB I Services	Fleet								
E-Mail:	@								
Signature authorized	1 by customer								