

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	163085 KM
File nr. :	1453589	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FBP126 / WAUZZZ8V2DA077323 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	16/05/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A3 SPORTBACK	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :	E	Environment Class:	EURO 5
Customer company :	SOA PEOPLE SA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK	Insurance certificate : [x]
Warning vest : [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD [x]
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	GOODYEAR	Tyre :	OK	>6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	DUNLOP	Tyre :	OK	2-4/	Rim :		/	Hubcap :
Wheel FR :	GOODYEAR	Tyre :	OK	>6/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	DUNLOP	Tyre :	OK	2-4/	Rim :	WHEEL SCRATCHED	/	Hubcap :
Wheel RES:	ANDERE	Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT MUDGUARD/RIGHT/FRONT	CHIPS
[x]	FRONT BUMPER/LEFT/SIDE	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/RIGHT/FRONT	CHIPS
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE	ONDERAAN			
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE				
	Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	+DEUK			
		Repair paint - LI	New paint - E		Depr.	Total
3	0 LU =0.00 EUR	254.68 EUR			50 %	254.68 EUR

Others

RIM FRONT RIGHT

	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
58.80	115.56	254.68	95.00	0	0	0	0	0	0
58.80	115.56	127.34	95.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
269.36	254.68	0	524.04
HOG: 0	BG: 1		NA Deprec. 396.70
			0.00%
			TOTAL 396.70

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 10/11/2017 Hour : 14:32 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	