

www.vabfleetservices.be Date: 10/11/2017 1/4

D9OMZ0

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	136471 KM
File nr. :	1456457	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GGL823 / WBA5C11010D03	33810 /	yr of constructionr :	/
E-File nr. :		First registration :	03/02/2014
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 5	Fuel type :	DIESEL
Object nr. :	62717	Fuel :	
Classification:	L	Environment Class:	EURO 6
Customer company :	Sonaca SA	Co2:	119g/km
Driver :		Remote controls:	2
Covering:	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

Variant car:	BERLINE	Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	4
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:		I	

Metallic paint:

Yes



www.vabfleetservices.be Date: 10/11/2017 2/4

Original registr. number :	OK		Service manual :		
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

		[x] V	Vidth	Ì		Н	eight	Ì	Туре		Rim	Index	
Wheel RES:	[x]		Tyre:		OK		/	Rim:			/ Hubcap:		
Wheel RR:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	Hubcap:		
Wheel FR:	[x]	BRIDGESTONE	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	Hubcap:		
Wheel RL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHEL	/ Hubcap:		
Wheel FL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHEE	/ Hubcap:		\Box

[x] Width		Height	Туре	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 10/11/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE

[x] FRONT MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

Interior

[x] CENTER CONSOLE OTHER DAMAGES

[x] DOOR IN REAR L CARVED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT BUMPER/LEFT SCRATCH WITH PAINT DAMAGE

 Repair paint - LI
 New paint - E
 Depr.
 Total

 1 0 LU = 0.00 EUR
 254.16 EUR
 50 %
 254.16 EUR

Others

RIM FRONT RIGHT

]	Number Code		Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
254.16	95.00	0	0	0	0	0	0	0	0
127.08	95.00	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
349.16	0	254.16	95.00
NA Deprec. 222.08		BG: 2	HOG: 0
0.00%		-	

TOTAL

222.08



10/11/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No)								
CIRCUMS	TANCES		NORMAL CONCLUSION						
Extra Time :	0 min	Waiting time: 0 m	in	Towing time :	0 min				
		Reason:		Reason:					
NOT EXECUTED :	: No								
Reason:									
Remark :									
Prices in EUR v	vithout VAT								
Authorized by		_	Executed by VAB Fleet Se	ervices					
customer :									
D 1 . 41 1									
Remark authorized	customer :								
Date :	10/11/2017	Hour: 16:33							
Company :									
Executed by VAB F Services	leet								
E-Mail :	@								
Signature authorized	by customer								