

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	121713 KM
File nr. :	1430517	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPI504 / WBA3D91050J219385 /		yr of constructionr :	/
E-File nr. :		First registration :	13/09/2013
VFS-nr. :		Color :	WHITE
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :	61232	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ELSTER NV/ESSEN	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 BER 316dA 116PK Aut.	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1995
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK			Service manual :			
Cert. of reg. / Part 1:	OK	[x]		Cert. of conformity :	OK		
Cert. of reg. copy / Part 2:				Insurance certificate :			
Warning vest :	OK	[x]		Transport licence :			
Tax certificate :				Navigation CD/SD/DVD	OK	[x]	
Fuel card :				Car radio :	OK	[x]	
Mobile phone kit :				Extinguisher :	OK	[x]	
				Warning triangle :	OK	[x]	
First aid kit :	OK	[x]		Oil level :	OK	[x]	
Jack, wheelspanner :				Filled up :	0		

Wheels and tyres: Summer tires

Wheel FL :	[x]	MICHELIN	Tyre :	OK	[x] >6 /	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x] 2-4 /	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK	[x] >6 /	Rim :	/	Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x] 2-4 /	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	60	R	16	H
Rear tyre		205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	WINDSCREEN/CENTER/RIGHT		WINDOW DAMAGE	HERSTELD	
Number	Code	Description	Unit price	Depr.	Total
0	0				
[x]	LIGHTS/RIGHT/FRONT		HOLE/CRACK/TORN	DAGLICHT	
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
2	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Interior

[x]	DOOR IN REAR L		HOLE		
Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-intvnl-01	VINYL REPAIR	82.20 EUR		82.20 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 6 specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		87.48 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	DAGLICHT	50.00 EUR	50 %	50.00 EUR

1	2	3	4	5	6	7	8	9	10
87.48	74.00	82.20	0	0	0	0	0	0	0
87.48	37.00	82.20	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
169.68	74.00	0	243.68
HOG: 0	BG: 0		NA Deprec. 206.68
			0.00%
			TOTAL 206.68

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 24/08/2017 Hour : 14:33 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	