

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	95594 KM
File nr. :	1458350	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HYT522 / WBA1C91050P873343 /		yr of constructionr :	/
E-File nr. :		First registration :	31/10/2014
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 1 HATCH	Fuel type :	DIESEL
Object nr. :	34695	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Ernst & Young Special Business Serv.CVBA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1: OK [x]	Cert. of conformity : OK
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] FULDA	Tyre : OK [x] 2-4/	Rim :	Hubcap : [x] SCRATCHED
Wheel RL : [x] FULDA	Tyre : OK [x] 2-4/	Rim :	Hubcap : [x] SCRATCHED
Wheel FR : [x] FULDA	Tyre : [x] OK [x] 2-4/	Rim :	Hubcap : [x] SCRATCHED
Wheel RR : [x] FULDA	Tyre : OK [x] 2-4/	Rim :	Hubcap : [x] SCRATCHED
Wheel RES: [x]	Tyre : OK /	Rim :	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	W
Rear tyre	205	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:	Tyre : OK /	Rim :	Hubcap :
Wheel RL :	Tyre : OK /	Rim :	Hubcap :
Wheel FR :	Tyre : OK /	Rim :	Hubcap :
Wheel RR :	Tyre : OK /	Rim :	Hubcap :
Wheel RES:	Tyre : OK /	Rim :	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/RIGHT/CENTER DENT
- [x] REAR DOOR/RIGHT/CENTER DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/SIDE/LEFTCENTER	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
1	0 LU =0.00 EUR		254.16 EUR		50 %
					254.16 EUR
[x]	ROOF/CENTER/RIGHT	OTHER DAMAGES			INWERKING
			Repair paint - LI	New paint - E	Depr.
					Total
3	0 LU =0.00 EUR		577.80 EUR		50 %
					577.80 EUR

Others

	HUB CAP FL				
			Repair paint - LI	New paint - E	Depr.
					Total
2	0 LU =0.00 EUR				50 %
	HUB CAP REAR L				
			Repair paint - LI	New paint - E	Depr.
					Total
2	0 LU =0.00 EUR				50 %
	HUB CAP REAR RIGHT				
			Repair paint - LI	New paint - E	Depr.
					Total
2	0 LU =0.00 EUR				50 %
	HUB CAP FR				
			Repair paint - LI	New paint - E	Depr.
					Total
2	0 LU =0.00 EUR				50 %

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR

1	2	3	4	5	6	7	8	9	10
254.16	144.00	577.80	0	0	0	0	0	0	0
127.08	72.00	288.90	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	975.96	0	975.96
HOG: 0	BG: 2		NA Deprec. 487.98
			0.00%
			TOTAL 487.98

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 15/11/2017 Hour : 11:36 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	