

www.vabfleetservices.be Date: 10/11/2017 1/4

DAM4YA

[X] EFFECTIVE [] NOT EXECUTED [] COLLECTION [] DELIVERY

[x] = Status Modification

Cleanliness: Commissionar: **KBC REMARKETING** INT: CLEAN [x] EXT: CLEAN [x] Owner: Mileage : 77721 KM File nr. : Mileage start / arrival: 0 / 01457184 Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1DQC318 / WBA3D11030F325788 / E-File nr. : First registration: 19/07/2012 Color: VFS-nr.: **BLACK** Make + Model : Fuel type : BMW / 3 **DIESEL** Object nr. : Fuel: Classification: **Environment Class:** EURO 5 Customer company: Co2: **KBC GROEP NV** 118g/km Driver : Remote controls: 2 TISSUE Covering: Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 0 Vehicle type: 3 BER 318d 136PK Country registration: **BELGIUM**

VAT over the margin - car:	No	Metallic paint:	Yes			
Variant car:	BERLINE	Engine size:	1995			
Gear box :	Manueel	Number of places:	5			
Number of gears:	6	Number of doors:	4			
HP:	136	kW:	100			
Fisc HP		Imported vehicle:				
Animals transported:	No	Smoked in vehicle:	No			
Due date vehicle inspection:		Extra set of tires:	No			
		Use:	Unknown			
General condition:						



www.vabfleetservices.be Date: 10/11/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

	Front	turo	,	225			50			D		17	W
l			[x] W	idth		Не	eight			Type		Rim	Index
Wheel R	ES:	[x]		Tyre:	OK		/	Rim:				/ Hubcap:	
Wheel R	R:	[x]	CONTINENTAL	Tyre:	OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel F	R:	[x]	CONTINENTAL	Tyre: [x]	OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel R	L:	[x]	CONTINENTAL	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	
Wheel F	L:	[x]	CONTINENTAL	Tyre:	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	/ Hubcap:	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	W
Rear tyre	225	50	R	17	W

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/	Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/	Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/	Hubcap :
Wheel RR:	Tyre:	OK	/	Rim:	/	Hubcap :
Wheel RES:	Tyre:	OK	/	Rim:	/	Hubcap :

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 10/11/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] ROOF/CENTER/LEFT OTHER DAMAGES TE POLIEREN

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] FRONT BUMPER/LEFT/SIDE SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR	-	50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	0	0	0	0	0	0	0	0	0
105.90	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
0	211.80	0		211.80
HOG: 0	BG: 0		NA Deprec.	105.90
			0.00%	

TOTAL 105.90



www.vabfleetservices.be Date: 10/11/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUM	STANCES		UNDER CONDITION - VEHICLE WET						
Extra Time :	0 min	Waiting time: 0 m Reason:	in	Towing time : Reason :	0 min				
NOT EXECUTED Reason :	D: No	I		I					
Remark :									
Prices in EUR	R without VAT								
Authorized by customer :			Executed by VA	B Fleet Services					
Remark authoriz	ed customer :								
Date :	10/11/2017	Hour: 12:56							
Company : Executed by VAE Services	3 Fleet								
E-Mail :	@								
Signature authoriz	ed by customer								