

www.vabfleetservices.be Date: 10/11/2017 1/4

D9F9VX

[X] EFFECTIVE	[] NOT EXECUTED	[X] COLLECTION	[] DELIVERY
---------------	------------------	----------------	--------------

[x] = Status Modification

VAT over the margin - car:

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner:		Mileage :	158163 KM
File nr. :	1456256	Mileage start / arrival:	0/0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GGO007 / WDD1760121J22	5980 /	yr of constructionr :	/
E-File nr. :		First registration :	03/02/2014
VFS-nr. :		Color :	SILVER
Make + Model :	MERCEDES / A	Fuel type :	DIESEL
Object nr. :	54316	Fuel:	
Classification:	N	Environment Class:	EURO 5
Customer company:	MERCEDES AALST	Co2:	102g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

		·	
Variant car:		Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	109	kW:	80
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Metallic paint:



Insurance certificate:

www.vabfleetservices.be Date: 10/11/2017 2/4

Original registr. number: OK Service manual:

Cert. of reg. / Part 1: OK [x] Cert. of conformity: OK

Cert. of reg. copy / Part 2:

Warning vest: OK [x] Transport licence:

Tax certificate : Navigation CD/SD/DVD

Fuel card : Car radio :

Mobile phone kit: Extinguisher: OK [x]

Warning triangle: OK [x]

First aid kit: OK [x] Oil level: OK [x]

Jack, wheelspanner: Filled up: 0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:
Wheel RL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:
Wheel FR:	[x]	BRIDGESTONE	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:
Wheel RR:	[x]	BRIDGESTONE	Tyre:		OK	[x]	4-6 /	Rim:	[x]	WHEEL SCRATCHED	/ Hubcap:
Wheel RES:	[x]		Tyre:		OK		/	Rim:			/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	225	45	R	17	V
Rear tyre	225	45	R	17	V

Remark:

Wheels and tyres:

	Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
	Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
1	Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x] Width		Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 10/11/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

[X] FRONT DOOR/LEFT/REAR SCRATCH WITH PAINT DAMAGE

[x] FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

[x] BONNET/CENTER/RIGHT/FRONT CHIPS

[x] FRONT BUMPER/CENTER/LEFT CHIPS

Interior

[x] BOOT LID IN CARVED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR DOOR/RIGHT/CORNER/BELOW SCRATCH WITH PAINT DAMAGE

	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

	1	2	3	4	5	6	7	8	9	10
	0	115.56	0	0	0	0	0	0	0	0
ſ	0	115.56	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL		
115.56	0	0		115.56
HOG: 0	BG: 0		NA Deprec.	115.56
			0.000/	

0.00%
TOTAL 115.56



10/11/2017 Date: www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES			UNDER CONDITION - VEHICLE WET					
Extra Time: 0 min		Waiting time: 0 mi Reason:	in	Towing time: 0 min Reason:				
NOT EXECUTED Reason:	: No	<u>'</u>						
Remark:								
Prices in EUR	without VAT							
Authorized by customer :			Executed by VAB Fleet So	ervices				
Remark authorized	l customer :							
Date :	10/11/2017	Hour: 14:44						
Company : Executed by VAB I Services	Fleet							
E-Mail :	@							
Signature authorized	1 by customer		1					