

[x] = Status Modification

## **APPRAISAL**

www.vabfleetservices.be Date: 29/03/2017 1/4

**ANHMOM** 

#### [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: CLEAN [x] Mileage : Owner: 64251 KM

File nr. : Mileage start / arrival: 1383119 0 / 0Reg number / Chassis / Ref: Mileag ref. service :

yr of constructionr: 1HVN813 / WDD1760121V034988 /

E-File nr. : First registration: 14/10/2014

VFS-nr.: Color: **SILVER** Make + Model : Fuel type : MERCEDES / A **DIESEL** 

Object nr. : Fuel: 4067

Classification: **Environment Class:** N EURO 5

Co2: **Customer company: ERNST & YOUNG** 98g/km

BEDRIJFSREVISOREN CVBA

Driver: Remote controls: 2

Covering: TISSUE Number keys : 2[x]Vehicle kind: VEHICLE Seats (minivan):

Vehicle type: Country registration: **BELGIUM** 

VAT over the margin - car: Metallic paint: Yes Variant car: **Engine size:** 1461 Gear box: Manueel Number of places: 5 Number of gears: 6 Number of doors: 5 HP: kW: 109 80 Fisc HP Imported vehicle: Animals transported: No Smoked in vehicle: No

Extra set of tires: Due date vehicle inspection: No

> Use: Unknown

0

General condition:



## **APPRAISAL**

www.vabfleetservices.be Date: 29/03/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

## Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel RL:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:				/ Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED	)	/ Hubcap:	
Wheel RES:	[x]		Tyre:		OK		/	Rim:				/ Hubcap:	
		[x]	Width			Н	eight	ĺ		Туре		Rim	Index
Fron	t tyre		205				55			R		16	M+S
Rear	tyre		205				55			R		16	M+S

#### Remark:

## Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

	[x]	Width	Height	Type	Rim	Index
Fron	ıt tyre	0	0	R	0	
Rear	r tyre	0	0	R	0	

#### Remark:



## **APPRAISAL**

www.vabfleetservices.be Date: 29/03/2017 3/4

### STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT CHIPS

[x] ROOF STYLE/CENTER/RECHTS DENT

#### STATUS: NOT ACCEPTABLE

#### Bodywork \& windows

[x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

1	2	3	4	5	6	7	8	9	10
211.80	0	0	0	0	0	0	0	0	0
105.90	0	0	0	0	0	0	0	0	0

	GENERAL	TRADITIONAL	INNOVATIVE
211.80	0	211.80	0
NA Deprec. 105.90		BG: 0	HOG: 0
0.00%			

TOTAL 105.90



# **APPRAISAL**

www.vabfleetservices.be Date: 29/03/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	STANCES	UNDER CONDITION - DUSTY VEHICLE						
Extra Time :	0 min	Waiting time : Reason :	0 min	Towing time : Reason :	0 min			
NOT EXECUTED Reason:	D: No			l				
Remark :								
Prices in EUR	without VAT							
Authorized by customer :			Executed by V	VAB Fleet Services				
Remark authorize	ed customer :							
Date :	29/03/2017	<b>Hour:</b> 14:24						
Company :  Executed by VAB Services	Fleet							
E-Mail :	@							
Signature authorize	ed by customer							
/								