

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: VERY DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	62007 KM
File nr. :	1456499	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GQX990 / SJNFAAJ11U1069358 /		yr of constructionr :	/
E-File nr. :		First registration :	04/04/2014
VFS-nr. :		Color :	BROWN
Make + Model :	NISSAN / QASHQAI	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ONBEKEND	Co2:	99g/km
Driver :		Remote controls:	1
Covering :	LEATHER	Number keys :	1 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	SUV	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	0-1.6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	[x]	NOK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	0-1.6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	45	R	19	W
Rear tyre	225	45	R	19	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	ROOF STYLE/CENTER/RECHTS	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/REAR	DENT
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/FRONT	DENT
[x]	FRONT THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
6	15 LU =72.00 EUR	0 EUR	235.80 EUR	50 %	307.80 EUR
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
5	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR
[x]	REAR WINDOW/RIGHT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
7	20 LU =96.00 EUR	0 EUR		50 %	96.00 EUR
[x]	REAR DOOR/LEFT/CENTER	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
4	30 LU =144.00 EUR	0 EUR	435.72 EUR	50 %	579.72 EUR
[x]	FRONT MUDGUARD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
3	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR

Interior

[x]	SEAT FL		CARVED			
		Repair paint - LI	New paint - E		Depr.	Total
2	20 LU =96.00 EUR	0 EUR			50 %	96.00 EUR

[x]	LUGGAGE COVER		MISSING/INCOMPLETE			
		Repair paint - LI	New paint - E		Depr.	Total
2	0 LU =0.00 EUR	0 EUR			50 %	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 10	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	145.80 EUR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-geur-01	ODOUR TREATMENT	152.58 EUR	152.58 EUR

TYRE REAR LEFT

		Repair paint - LI	New paint - E		Depr.	Total
9	5 LU =24.00 EUR				50 %	24.00 EUR

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
8	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
8	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
8	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
8	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces					
Number	Code	Description	Unit price	Depr.	Total
2	1	LUGGAGE COVER	240.00 EUR	50 %	240.00 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	DOOR REAR LEFT	367.20 EUR	50 %	367.20 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	SIDE PROTECTION	40.00 EUR	50 %	40.00 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	WHEEL HUL	60.00 EUR	50 %	60.00 EUR
Number	Code	Description	Unit price	Depr.	Total
6	1	REAR BUMPER	343.20 EUR	50 %	343.20 EUR
Number	Code	Description	Unit price	Depr.	Total
7	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	SEAT UPHOLSTERY LEATHER	240.00 EUR	50 %	240.00 EUR
Number	Code	Description	Unit price	Depr.	Total
9	1	TYRE	108.00 EUR	50 %	108.00 EUR

1	2	3	4	5	6	7	8	9	10
298.38	576.00	220.18	1046.92	308.20	651.00	346.00	380.00	132.00	0
298.38	288.00	110.09	523.46	154.10	325.50	173.00	380.00	66.00	0

INNOVATIVE	TRADITIONAL	GENERAL	
678.38	3280.30	0	3958.68
HOG: 0	BG: 0		NA Deprec. 2318.53
			0.00%
			TOTAL 2318.53

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/11/2017 Hour : 11:44 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	