

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	102514 KM
File nr. :	1455290	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FPQ762 / U5YPC815ADL229003 /		yr of constructionr :	/
E-File nr. :		First registration :	01/01/1918
VFS-nr. :		Color :	BEIGE
Make + Model :	KIA / SPORTAGE	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	SHERPA.BE NV	Co2:	g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	SPORTAGE 2WD iTouch 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:		kW:	
Fisc HP		Imported vehicle:	
Animals transported:	Yes	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : NOK [x] MISSING/INCOMPLETE
Cert. of reg. / Part 1: NOK [x] MISSING/INCOMPLETE	Cert. of conformity : NOK [x] MISSING/INCOMPLETE
Cert. of reg. copy / Part 2:	Insurance certificate : [x]
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD OK [x]
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner : OK	Oil level : OK
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] KLÉBER Tyre : OK 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RL : [x] CONTINENTAL Tyre : OK 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] KLÉBER Tyre : OK 4-6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] CONTINENTAL Tyre : OK 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	225	60	R	17	H
Rear tyre	225	60	R	17	H

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	REAR BUMPER/SIDE/LEFTCENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	REAR DOOR/LEFT/CENTER	DENT
[x]	FRONT DOOR/RIGHT/CENTER	DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES	CHEMISCHE INWERKING	
		Repair paint - LI	New paint - E	
		Depr.	Total	
2	0 LU =0.00 EUR	290.08 EUR	50 %	290.08 EUR
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	
		Depr.	Total	
3	0 LU =0.00 EUR	211.80 EUR	50 %	211.80 EUR

Interior

[x]	FLOOR BOOT	DIRTY			
	Number Code	Description	Unit price	Depr.	Total
1	I 2	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	29.16 EUR

1	2	3	4	5	6	7	8	9	10
29.16	290.08	211.80	0	0	0	0	0	0	0
29.16	145.04	105.90	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
29.16	501.88	0	531.04
HOG: 0	BG: 0		NA Deprec. 280.10
			0.00%
			TOTAL 280.10

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : GEEN BOORDDOCUMENTEN/ID FICTIEF [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/11/2017 Hour : 10:53 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	