

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	186041 KM
File nr. :	1458872	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EKZ780 / VF1KZ140648229472 /		yr of constructionr :	/
E-File nr. :		First registration :	10/01/2013
VFS-nr. :		Color :	BLACK
Make + Model :	RENAULT / MEGANE BREAK	Fuel type :	DIESEL
Object nr. :	12213	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ATOS WORLDLINE NV	Co2:	90g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	MEGANE GT Energy Dynamique 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK			Service manual :	OK	[x]
Cert. of reg. / Part 1:				Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :		
Warning vest :	OK	[x]		Transport licence :		
Tax certificate :				Navigation CD/SD/DVD	OK	[x]
Fuel card :				Car radio :	OK	[x]
Mobile phone kit :				Extinguisher :	OK	[x]
				Warning triangle :	OK	[x]
First aid kit :	OK	[x]		Oil level :	OK	[x]
Jack, wheelspanner :				Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	SEMPERIT	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel FR :	[x]	SEMPERIT	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :		

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	55	R	16	V
Rear tyre		205	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	FRONT MUDGUARD/LEFT/CENTER	DENT	
[x]	FRONT BUMPER/RIGHT/CORNER	SCRATCH (WITHOUT PAINT DAMAGE)	POLIEREN

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.
				Total
5	0 LU =0.00 EUR	211.80 EUR		50 %
				211.80 EUR
[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	+DEUK	
		Repair paint - LI	New paint - E	Depr.
				Total
4	0 LU =0.00 EUR	308.20 EUR		50 %
				308.20 EUR
[x]	REAR MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	+DEUK	
		Repair paint - LI	New paint - E	Depr.
				Total
6	0 LU =0.00 EUR	308.20 EUR		50 %
				308.20 EUR
[x]	ROOF/CENTER/RIGHT	OTHER DAMAGES	CHEM. INWERKING + DEUK	
		Repair paint - LI	New paint - E	Depr.
				Total
9	0 LU =0.00 EUR	481.50 EUR		50 %
				481.50 EUR
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	+DEUK	
		Repair paint - LI	New paint - E	Depr.
				Total
7	0 LU =0.00 EUR	318.35 EUR		50 %
				318.35 EUR
[x]	FRONT THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	BINNENIN	
		Repair paint - LI	New paint - E	Depr.
				Total
2	0 LU =0.00 EUR	310.50 EUR		50 %
				310.50 EUR

[x]	WINDOW STYLE FRONT DOOR/RIGHT/REAR		DENT			
		Repair paint - LI	New paint - E	Depr.	Total	
8	0 LU =0.00 EUR	0 EUR		50 %		
		Repair paint - LI	New paint - E	Depr.	Total	
8	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR	
[x]	BONNET/CENTER/LEFT		DENT			
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR	
[x]	BONNET/CENTER/RIGHT		DENT			
	Number	Code	Description	Unit price	Depr.	Total
0	0					

Interior

[x]	SEAT FL			HOLE		
	Number	Code	Description	Unit price	Depr.	Total
10	I 1	i-vab-intvlr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR		64.32 EUR
[x]	LUGGAGE COVER			MISSING/INCOMPLETE		
			Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR		0 EUR		50 %	

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 5	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		72.90 EUR

RIM FRONT LEFT

	Number	Code	Description	Unit price	Depr.	Total
10	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR LEFT

	Number	Code	Description	Unit price	Depr.	Total
10	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

	Number	Code	Description	Unit price	Depr.	Total
10	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
10	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
8	1	RUITSTIJL	60.00 EUR	50 %	60.00 EUR

Number	Code	Description	Unit price	Depr.	Total
10	1	LUGGAGE COVER	240.00 EUR	50 %	240.00 EUR

1	2	3	4	5	6	7	8	9	10
72.90	310.50	290.08	308.20	211.80	308.20	318.35	84.00	481.50	684.32
72.90	155.25	145.04	154.10	105.90	154.10	159.18	42.00	240.75	564.32

INNOVATIVE	TRADITIONAL	GENERAL	
517.22	2552.63	0	3069.85
HOG: 0	BG: 0		NA Deprec. 1793.54
			0.00%
			TOTAL 1793.54

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/11/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	