

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	123298 KM
<b>File nr. :</b>	1455454	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1GRE911 / YV1MV8481E2151660 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	07/04/2014
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	VOLVO / V40	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	76409	<b>Fuel :</b>	
<b>Classification :</b>	F	<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	AKKA BELGIUM	<b>Co2:</b>	88g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1560
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	114	<b>kW:</b>	84
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	1.6-2/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	BROKEN DOWN / DAMAGED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	1.6-2/	Rim :	[x]	BROKEN DOWN / DAMAGED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	[x]	NOK	/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	V
Rear tyre	205	55	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	REAR WINDOW/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE

### Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	-------------------------------	---------------------------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
6	10 LU =48.00 EUR		211.80 EUR		50 %
					259.80 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
7	0 LU =0.00 EUR		308.20 EUR		50 %
					308.20 EUR
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
7	0 LU =0.00 EUR		318.35 EUR		50 %
					318.35 EUR
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
7	0 LU =0.00 EUR		318.35 EUR		50 %
					318.35 EUR
[x]	FRONT THRESHOLD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			BINNEN
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
9	I 1 i-vab-sp-01	SPOTREPAIR		115.56 EUR	
					115.56 EUR
[x]	FRONT MUDGUARD/RIGHT/FRONT	HOLE/CRACK/TORN			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
7	15 LU =72.00 EUR		220.18 EUR		50 %
					292.18 EUR
[x]	LIGHTS/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
4	I 1 i-vab-pol-01	POLISH SCRATCH (<15CM)		43.44 EUR	
					43.44 EUR

[x]	LIGHTS/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
	4	I 1 i-vab-pol-01	POLISH SCRATCH (<15CM)	43.44 EUR		43.44 EUR
[x]	FRONT BUMPER/CENTER/RIGHT		DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
	3	20 LU =96.00 EUR	0 EUR	235.80 EUR	50 %	331.80 EUR
[x]	ROOF/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
	5	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR

## Interior

[x]	CARPET FL		CARVED			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
	1	40 LU =192.00 EUR	0 EUR		50 %	192.00 EUR
[x]	SEAT FL		BURNT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
	1	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	ROOF UPHOLSTERY		BURNT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
	1	3 LU =14.40 EUR	0 EUR		50 %	14.40 EUR

## Others

### CLEANLINESS INTERIOR

	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
	1	I 1 i-vab-geur-01	ODOUR TREATMENT	152.58 EUR		152.58 EUR

### TYRE SPARE WHEEL

			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
	2	0 LU =0.00 EUR			50 %	

### RIM FRONT LEFT

	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
	8	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

### RIM REAR RIGHT

			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
	8	5 LU =24.00 EUR			50 %	24.00 EUR

RIM FRONT RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
8	5 LU =24.00 EUR		50 %	24.00 EUR

## Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SEAT UPHOLSTERY TISSUE	120.00 EUR	50 %	120.00 EUR
1	1	CARPET	60.00 EUR	50 %	60.00 EUR
1	1	BEKLEDING A_STIJL	50.00 EUR	50 %	50.00 EUR
2	1	REPAIR KIT TYRES	210.53 EUR	50 %	210.53 EUR
3	1	FRONT BUMPER	403.20 EUR	50 %	403.20 EUR
3	1	FRONT	100.00 EUR	50 %	100.00 EUR
3	1	BUMPER GRID	50.00 EUR	50 %	50.00 EUR
6	1	REAR LIGHT	30.00 EUR	50 %	30.00 EUR
8	1	ALLOY WHEEL	211.20 EUR	50 %	211.20 EUR
8	1	ALLOY WHEEL	211.20 EUR	50 %	211.20 EUR

1	2	3	4	5	6	7	8	9	10
708.98	210.53	885.00	86.88	481.50	289.80	1237.08	565.40	115.56	0
430.78	105.26	442.50	86.88	240.75	144.90	618.54	330.20	115.56	0

INNOVATIVE	TRADITIONAL	GENERAL	
450.02	4130.71	0	<b>4580.73</b>
HOG: 0	BG: 0		NA Deprec. 2515.38
			0.00%
			<b>TOTAL 2515.38</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 14/11/2017 <b>Hour :</b> 11:16 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
<b>Signature authorized by customer</b>  	