

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	148077 KM
File nr. :	1458875	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EEO294 / VF38ERHH8CL065186 /		yr of constructionr :	/
E-File nr. :		First registration :	08/11/2012
VFS-nr. :		Color :	BROWN D
Make + Model :	PEUGEOT / 508	Fuel type :	DIESEL
Object nr. :	12406	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	GEA PROCESS ENGINEERING/COURTOY (HALLE)	Co2:	130g/km
Driver :		Remote controls:	2
Covering :	IMITATION LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	508 SW Allure 163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1997
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] SEMPERIT Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] SEMPERIT Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel FR : [x] SEMPERIT Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] SEMPERIT Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	45	R	18	W
Rear tyre	235	45	R	18	W

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT OTHER DAMAGES SLECHT HERSTELD

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x] REAR WINDOW STYLE/CENTER/LEFT/UP OTHER DAMAGES INWERKING

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	150.00 EUR		50 %	150.00 EUR

[x] FRONT THRESHOLD/RIGHT/CENTER DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR

[x] BONNET/CENTER/LEFT OTHER DAMAGES INWERKING

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR

Accessories and others

[x] OUTSIDE MIRROR LEFTHAND SIDE WINDOW DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1 PINKER		15.00 EUR	50 %	15.00 EUR

1	2	3	4	5	6	7	8	9	10
440.08	310.50	39.00	95.00	0	0	0	0	0	0
220.04	155.25	19.50	95.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	789.58	0	884.58
HOG: 0	BG: 0		NA Deprec. 489.79
			0.00%
			TOTAL 489.79

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 15/11/2017 Hour : 15:16 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	