

www.vabfleetservices.be Date: 14/11/2017 1/4

DC0IGH

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION []

[] DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness:	INT: CLEAN [x] EXT: CLEAN [x]
Owner:		Mileage :	137530 KM
File nr. :	1458325	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FUY029 / WVWZZZ3CZEE	043880 /	yr of constructionr :	/
E-File nr. :		First registration :	04/11/2013
VFS-nr. :		Color :	BLACK
Make + Model :	VOLKSWAGEN / PASSAT	Fuel type :	DIESEL
Object nr. :	12282	Fuel:	
Classification:		Environment Class:	EURO 5
Customer company :	CEGEKA NV	Co2:	116g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	PASSAT VAR Highline BMT 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes				
Variant car:	BREAK	Engine size:	1598				
Gear box :	Manueel	Number of places:	5				
Number of gears:	6	Number of doors:	5				
нр:	105	kW:	77				
Fisc HP		Imported vehicle:					
Animals transported:	No	Smoked in vehicle:	No				
Due date vehicle inspection:		Extra set of tires:					
		Use:	Unknown				
General condition:	General condition:						



www.vabfleetservices.be Date: 14/11/2017 2/4

Original registr. number : OK Service manual: OK Cert. of reg. / Part 1: OK Cert. of conformity: OK Insurance certificate : Cert. of reg. copy / Part 2: [x] OK Warning vest: Transport licence: Tax certificate: Navigation CD/SD/DVD Fuel card : Car radio: OK Mobile phone kit: Extinguisher: OK Warning triangle: OK

Oil level:

OK

0

First aid kit : OK

Jack, wheelspanner: Filled up:

Wheels and tyres: Summer tires

Wheel FL: CONTINENTAL Tyre: OK WHEEL SCRATCHED 4-6/ Rim: Hubcap: Wheel RL: CONTINENTAL Tyre: OK 4-6/ Rim: WHEEL SCRATCHED / Hubcap: Wheel FR: CONTINENTAL Tyre: OK 4-6/ Rim: WHEEL SCRATCHED / Hubcap: Wheel RR: CONTINENTAL Tyre: OK 4-6/ Rim: WHEEL SCRATCHED / Hubcap: Wheel RES: Tyre: OK Rim: / Hubcap:

	Width	Height	Type	Rim	Index
Front tyre	235	45	R	17	W
Rear tyre	235	45	R	17	W

Remark:

Wheels and tyres:

Wheel FL: Tyre: OK Rim: / Hubcap: Wheel RL: OK Tyre: Rim: / Hubcap: Wheel FR: OK Tyre: Rim: / Hubcap: Wheel RR: Tyre: OK Rim: / Hubcap: Wheel RES: OK Tyre: Rim: / Hubcap:

	Width	Height	Туре	Rim	Index
Front tyre	0	0		0	
Rear tyre	0	0		0	

Remark:



www.vabfleetservices.be Date: 14/11/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows					
[x]	REAR MUDGUARD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE			
[x]	ROOF/CENTER/LEFT	CHIPS			
[x]	REAR DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE RAND			
[x]	FRONT DOOR/LEFT/REAR	DENT			

DENT

Interior

[x]

BOOT LID IN SCRATCHED

STATUS: NOT ACCEPTABLE

FRONT DOOR/LEFT/CENTER

Bodywork \& windows

[x] REAR MUDGUARD/RIGHT/FRONT DENT

]	Number	Code	Description	Unit price	Depr. Total	
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR	63.00 EUR	

1	2	3	4	5	6	7	8	9	10
63.00	0	0	0	0	0	0	0	0	0
63.00	0	0	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
63.00		0	0	63.00
63.00	NA Deprec.		BG: 0	HOG: 0
	0.00%			
63.00	TOTAL			



www.vabfleetservices.be Date: 14/11/2017 4/4

[x] = Status Modification

Pictures: No

CIRCUMSTANCES			NORMAL CONCLUSION				
Extra Time :	0 min	Waiting t	ime: 0 min		Towing time : Reason :	0 min	
NOT EXECUTED : Reason :	No	I					
Remark :							
Prices in EUR v	vithout VAT						
Authorized by customer :				Executed by VAB Floor	eet Services		
Remark authorized	customer :						
Date :	14/11/2017	Hour :	13:47				
Company: Executed by VAB For Services	leet						
E-Mail:	@						
Signature authorized	by customer		_				