

www.vabfleetservices.be Date: 10/11/2017 1/4

D9CAPF

### [X] EFFECTIVE [ ] NOT EXECUTED [X] COLLECTION [ ] DELIVERY

[x] = Status Modification

Commissionar: KBC REMARKETING Cleanliness: INT: CLEAN [x] EXT: DIRTY [x]

Owner: Mileage: 101797 KM

File nr.: 1456193 Mileage start / arrival: 0 / 0

Reg number / Chassis / Ref: Mileage ref. service: 0

1ECI296 / YV1MV8481D2016293 / yr of constructionr: /

E-File nr.: First registration: 18/10/2012

VFS-nr.: Color: GREY

Make + Model: VOLVO / V40 Fuel type: DIESEL

Object nr.: 2889 Fuel:

Classification: Environment Class: EURO 5

Customer company: NEVEN-LEMMENS PLASTICS NV Co2: 94g/km

Driver: Remote controls: 2

Covering: TISSUE Number keys: 2 [x]

Vehicle kind: VEHICLE Seats (minivan): 0

Vehicle type: V40 D2 Base 115PK Country registration: BELGIUM

Metallic paint: VAT over the margin - car: No Yes **BREAK** 1560 Variant car: Engine size: Gear box : Number of places: 5 Manueel Number of gears: 6 Number of doors: 5 HP: kW: 114 84 Fisc HP Imported vehicle: Animals transported: No Smoked in vehicle: No Due date vehicle inspection: Extra set of tires: No Use: Unknown

General condition:



www.vabfleetservices.be Date: 10/11/2017 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:			Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest:	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD	OK	[x]
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

## Wheels and tyres: Summer tires

		[x] Width		_	Height			Туре		Rim	Index		
		[]	7:J+L			ш	iaht		Trme		D:	Indov	
Wheel RES:	[x]		Tyre:		OK		/	Rim:		/	Hubcap:		
Wheel RR:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:		
Wheel FR:	[x]	BRIDGESTONE	Tyre:	[x]	OK	[x]	1.6-2 /	Rim:		/	Hubcap:		
Wheel RL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	2-4 /	Rim:		/	Hubcap:		
Wheel FL:	[x]	BRIDGESTONE	Tyre:		OK	[x]	1.6-2 /	Rim:		/	Hubcap:		

[x]	Width	Height	Туре	Rim	Index
Front tyre	205	50	R	17	W
Rear tyre	205	50	R	17	W

Remark:

## Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

 [x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 10/11/2017 3/4

#### STATUS: ACCEPTABLE / USAGE DAMAGE

#### Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

[x] BONNET/CENTER/LEFT/FRONT CHIPS

#### STATUS: NOT ACCEPTABLE

#### Bodywork \& windows

[x] FRONT BUMPER/RIGHT DENT

 Repair paint - LI
 New paint - E
 Depr.
 Total

 1 0 LU = 0.00 EUR
 211.80 EUR
 50 %
 211.80 EUR

#### Interior

[x] DOOR IN FL DIRTY

	Number	Code	Description	Unit price	Depr.	Total
1	I 1	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		14.58 EUR

1	2	3	4	5	6	7	8	9	10
226.38	0	0	0	0	0	0	0	0	0
120.48	0	0	0	0	0	0	0	0	0

	INNOVATIVE	TRADITIONAL	GENERAL		
ĺ	14.58	211.80	0	226.3	38
	HOG: 0	BG: 0		NA Deprec. 120.	48

0.00%
TOTAL 120.48



Date: 10/11/2017 www.vabfleetservices.be 4/4

[x] = Status Modification

Pictures: No

CIRCUMS	TANCES		UNDER CONDITION - VEHICLE WET					
Extra Time :	0 min	Waiting time: 0 m Reason:	in	Towing time : Reason :	0 min			
NOT EXECUTED : Reason :	No	<b>'</b>						
Remark:								
Prices in EUR v	vithout VAT							
Authorized by customer :			Executed by VAB Fleet S	ervices				
Remark authorized	customer :							
Date :	10/11/2017	<b>Hour:</b> 14:44						
Company :								
Executed by VAB F Services	leet							
E-Mail :	@							
Signature authorized	by customer							