

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	113803 KM
File nr. :	1457175	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FUF172 / WVWZZZ6RZEY094263 /		yr of constructionr :	/
E-File nr. :		First registration :	25/10/2013
VFS-nr. :		Color :	GREY
Make + Model :	VOLKSWAGEN / POLO	Fuel type :	DIESEL
Object nr. :	73891	Fuel :	
Classification :	A	Environment Class:	EURO 5
Customer company :	S. OLIVER BENELUX BV	Co2:	96g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	[x]	Insurance certificate :	
Warning vest :	OK	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :		/	Hubcap :
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :		/	Hubcap :
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	[x]	/	Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK		/	Rim :	[x]	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	185	60	R	15	H
Rear tyre	185	60	R	15	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/LEFT/Front	DENT
[x]	REAR THRESHOLD/RIGHT/REAR	DENT
[x]	BONNET/CENTER/RIGHT/Front	CHIPS
[x]	FRONT BUMPER/LEFT	SCRATCH WITH PAINT DAMAGE
[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE

Accessories and others

[x]	VEH COVERED WITH STICKERS	STICKER(S)
-----	---------------------------	------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT			
			Repair paint - LI	New paint - E	Depr.
					Total
1	15 LU =72.00 EUR		246.56 EUR		50 %
					318.56 EUR
[x]	WINDSCREEN/RIGHT	WINDOW DAMAGE			<5CM VAN RAND
			Repair paint - LI	New paint - E	Depr.
					Total
2	25 LU =120.00 EUR		0 EUR		50 %
					120.00 EUR

Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WIND SCREEN	293.76 EUR	50 %	293.76 EUR

1	2	3	4	5	6	7	8	9	10
318.56	413.76	95.00	0	0	0	0	0	0	0
159.28	206.88	95.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	732.32	0	827.32
HOG: 0	BG: 1		NA Deprec. 461.16
			0.00%
			TOTAL 461.16

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 16/11/2017 Hour : 09:32 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	