


MERCEDES A: 1HLK886

Vinnumber:	WDD1760121V022320	Versionname:	A 180CDI BE Edition 109PK
First Registrationdate:	20/08/2014	Fiscalpower:	
Expertise Mileage:	80620	Power Kw:	80
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2816
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

	195/65/15/91 V Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	440,74
Bumper F R, Scratch(es), It - Spot repair	115,56



Bonnet, Bump(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Door R R, Bump(s), PDR - Knock out without painting	63,00
-----------------------------------------------------	-------



Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---------------------------------------------------------	--------



Wheel cover F R, Scratch(es), E - Replace 30,00



Bumper R, Bad repair, Acceptable 0,00



Seat cover F L, Stain, Forfeit 12,00

