



## VOLKSWAGEN Caddy: 710AKQ

|                         |                          |              |                              |
|-------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber:             | <b>WV2ZZZ2KZ9X106898</b> | Versionname: | <b>CADDY Maxi Life 105PK</b> |
| First Registrationdate: | <b>1/04/2009</b>         | Fiscalpower: |                              |
| Expertise Mileage:      | <b>139305</b>            | Power Kw:    | <b>77</b>                    |
| Bodytype:               |                          | Body color   | <b>White</b>                 |
| Gearbox:                | <b>MAN 5 VIT</b>         | Paint type   | <b>Opaque</b>                |
| Transmission:           | <b>Front</b>             | Rims summer  | <b>Steel</b>                 |
| Fueltype:               | <b>Diesel</b>            | Oil level    | <b>OK</b>                    |
| Battery functioning     | <b>Yes</b>               | Parking lot  | <b>3413</b>                  |
| Number of doors         | <b>5</b>                 |              |                              |
| Number of seats         | <b>5</b>                 |              |                              |
| Number head rests       | <b>5</b>                 |              |                              |
| Rims summer             | <b>Steel</b>             |              |                              |
| Category                | <b>Passenger Car</b>     |              |                              |
| Oil level               | <b>OK</b>                |              |                              |

## Options

|                         |                               |
|-------------------------|-------------------------------|
| Radio CD                | Central consol F              |
| Windows electric F      | Rear parking sensors          |
| Cruise Control          |                               |
| Type of headlighting    | <b>Headlighting Halogen</b>   |
| Type of Lining          | <b>Lining fabrics</b>         |
| Type of climate control | <b>Manual climate control</b> |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Idle position       | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Lighting            | <b>OK</b>  |
| Transmission        | <b>OK</b> | Wiperblades         | <b>OK</b>  |
| Handbrake           | <b>OK</b> |                     |            |

## Degree of wear

| 205/55/16/91 H Steel |       |                       |       |                       |
|----------------------|-------|-----------------------|-------|-----------------------|
| Summer tyres:        | Fr.L. | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|                      | Re.L. | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

## Assistance equipment

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>411,78</b> |
|-------------------|---------------|

|  |             |
|--|-------------|
| Wheel cover R L, Scratch(es), Acceptable | <b>0,00</b> |
|--|-------------|

No pictures to display

|                                    |             |
|------------------------------------|-------------|
| Front bumper, Repaired, Acceptable | <b>0,00</b> |
|------------------------------------|-------------|



|                                    |             |
|------------------------------------|-------------|
| Wing F R, Scratch(es), 67 - Polish | <b>0,00</b> |
|------------------------------------|-------------|

No pictures to display

|                                |             |
|--------------------------------|-------------|
| Bumper R, Repaired, Acceptable | <b>0,00</b> |
|--------------------------------|-------------|

No pictures to display

|   |              |
|---|--------------|
| Wheel cover R R, Scratch(es), E - Replace | <b>22,50</b> |
|---|--------------|



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Sill outer L, Bump(s), LI - Repair and paint (complete) 304,88



Wheel cover F R, Missing, E - Replace 22,50



Tailgate, Bump(s), Acceptable 0,00

No pictures to display

Wheel cover F L, Missing, E - Replace 22,50



Interior, Damaged, Acceptable 0,00



Trunk lid covering R, Broken, E - Replace 39,40

