



VOLVO S60: 1DVL985

Vinnumber:	YV1FS84A1D2189770	Versionname:	S60 BER D2 Kinetic St/St
First Registrationdate:	10/09/2012	Fiscalpower:	115PK
Expertise Mileage:	112562	Power Kw:	84
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Body color:	MET.
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	OK	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1422
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Front parking sensors
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

205/60/16/96 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 373,54

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bump(s), Acceptable 0,00

No pictures to display








Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Backrest cover F L, Worn, P - Check 0,00



Bumper R, Scratch(es), Acceptable 0,00

<i>No pictures to display</i>		
Roof, Chemical polution, 67 - Polish		55,19
		
Door F L, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Outer door handle R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Scratch(es), LI - Repair and paint (complete)		318,35
		
Wing F L, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Repaired, P - Check		0,00
		
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		