



BMW 1: 1GDV448

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------|
| Vinnumber: | WBA1D11020J820942 | Versionname: | 1 SPORTSHATCH 116i |
| First Registrationdate: | 10/01/2014 | Fiscalpower: | 136PK |
| Expertise Mileage: | 133153 | Power Kw: | 100 |
| Bodytype: | Hatchback | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Petrol | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2325 |
| Battery functioning: | Yes | | |
| Number of doors: | 3 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of Lining: | Lining Alcantara |
| Type of climate control: | Autom climate control |
| Sport seats | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear









| | | | | |
|---------------|----------------------------------|---------------------|-------|---------------------|
| | 225/45/17/91 W LightMetal | | | |
| Summer tyres: | Fr.L. | Dunlop: 3 mm | Fr.R. | Dunlop: 3 mm |
| | Re.L. | Dunlop: 2 mm | Re.R. | Dunlop: 2 mm |

Assistance equipment

| | | |
|--|---------|----------------|
| | Runflat | Yes |
| Total cost ex VAT | | 1567,88 |
| Door F L, Bump(s), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | | 95,00 |



| | | |
|---|--|-------------|
| Backrest cover F R, Scratch(es), Acceptable | | 0,00 |
|---|--|-------------|

| | |
|--|--------|
| Backrest cover F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|  | |
| Centre console, Damaged, Acceptable | 0,00 |
|  | |
| Bumper Trim F, Missing, Le - Replace and paint | 123,38 |
|  | |
| Wing R R, Bump(s), Acceptable | 0,00 |
|  | |
| Wing R L, Chemical polution, LI - Repair and paint (complete) | 308,20 |
|  | |
| Roof, Chemical polution, LI - Repair and paint (complete) | 481,50 |
|  | |
| Wing F R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|  | |
| Door F R, Bump(s), PDR - Knock out without painting | 63,00 |
|  | |
| Wing R L, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door frame F R, Scratch(es), Acceptable | 0,00 |



| | |
|--|-------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



| | |
|--|------|
| Bonnet, Chemical pollution, Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|--|-------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|

