

**BMW X3: 1FXW324**

| | | | |
|-----------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber: | WBAWY110800C53011 | Versionname: | X3 sDrive18 143PK Aut. |
| First Registrationdate: | 2/12/2013 | Fiscalpower: | |
| Expertise Mileage: | 90428 | Power Kw: | 105 |
| Bodytype: | SUV | Body color | Dark Brown |
| Gearbox: | Automatic | Paint type | Metalic |
| Transmission: | Back | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Battery functioning | Yes | Parking lot | 4507 |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|--|
| Radio CD | | Seats electric F L | |
| Windows electric F | | Seats electric F R | |
| Windows electric R | | Central consol F | |
| Cruise Control | | Luggage cover | |
| Steering wheel multifunctional | | Rear parking sensors | |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Sound engine | OK |
| Idle position | OK | Clutch test | OK |
| Engine startingtime | OK | Wiper fluid level | OK |
| Exhaust gass | OK | Lighting | OK |
| Transmission | OK | Wiperblades | OK |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|-----------------------------------|----------------------|-------|----------------------|
| | 245/50/17/100 H LightMetal | | | |
| Winter tyres: | Fr.L. | Pirelli: 6 mm | Fr.R. | Pirelli: 6 mm |
| | Re.L. | Pirelli: 5 mm | Re.R. | Pirelli: 5 mm |

Assistance equipment

| | |
|---------------------------------------|------|
| Total cost ex VAT | 0,00 |
| Door F R, Bad repair, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R R, Repaired, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Front bumper, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Windscreen, Repaired, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |