



VOLVO S80: 1DHY856			
Vinnnumber:	YV1A588A1C1162741	Versionname:	S80 D3 Kinetic St/St 163PK
First Registrationdate:	23/05/2012	Fiscalpower:	
Expertise Mileage:	76376	Power Kw:	120
Bodytype:	Berline	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2719
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
GPS storage		Rear parking sensors	
GPS storage	HD	Type of Tow bar	Tow bar fixed
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	245/45/17/91 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2476,32
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00
---	--	--	--------------



			95,00
--	--	--	--------------

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84



Seat cover F L, Damaged, Acceptable 0,00



Bonnet, Scratch(es), LI - Repair and paint (complete) 348,09



Wing F R, Chemical polution, LI - Repair and paint (complete) 264,21



Front bumper, Bump(s), It - Spot repair 115,56



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Chemical polution, LI - Repair and paint (complete) 362,02



Windscreen, Stone chip(s), Windscreen repair 58,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical polution, LI - Repair and paint (complete) 577,80



Door F R, Scratch(es), Acceptable 0,00

No pictures to display