



<b>VOLKSWAGEN Touran: 1EFH415</b>			
Vinnnumber:	<b>WVGZZZ1TZDW051694</b>	Versionname:	<b>TOURAN Trendline BMT Start/Stop 105PK</b>
First Registrationdate:	<b>15/11/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>152535</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3407</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar fixed</b>
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Sound engine	<b>OK</b>
Idle position	<b>OK</b>	Clutch test	<b>OK</b>
Engine startingtime	<b>OK</b>	Wiper fluid level	<b>OK</b>
Exhaust gass	<b>OK</b>	Lighting	<b>OK</b>
Transmission	<b>OK</b>	Wiperblades	<b>OK</b>
Handbrake	<b>OK</b>		

<b>Degree of wear</b>				
	<b>205/55/16/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Firestone: 3 mm</b>	Fr.R.	<b>Firestone: 3 mm</b>
	Re.L.	<b>Firestone: 4 mm</b>	Re.R.	<b>Firestone: 4 mm</b>












<b>Assistance equipment</b>	
Total cost ex VAT	0,00
Rear window, Scratch(es), E - Replace	0,00



Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Boot carpet, Dirty, Cleaning	24,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------

			Internal Boot Lining L, Scratch(es), Smart repair	110,64
			Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
			Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
			Alloy rim F R, Scratch(es), Acceptable	0,00

No pictures to display