



BMW X5: SF8154			
Vinnumber:	WBAZW810X00C13816	Versionname:	3.0 M50D 4WD AUTO
First Registrationdate:	13/05/2013	Fiscalpower:	
Expertise Mileage:	56577	Power Kw:	280
Bodytype:	SUV	Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	4 Weel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1523
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
	255/50/19/107 W LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm












Assistance equipment	
Total cost ex VAT	0,00
Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84



Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

	Wing F R, Scratch(es), LI - Repair and paint (complete)	264,21
	Wing F L, Scratch(es), LI - Repair and paint (complete)	264,21
	Bumper R, Bump(s) and scratch(es), Le - Replace and paint	766,80
	Blinker F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
	Windscreen, Crack, E - Replace	0,00
	Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	Door F R, Scratch(es), LI - Repair and paint (complete)	382,02
	Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Wing R L, Scratch(es), LI - Repair and paint (complete)	369,84
	Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09



Door R L, Scratch(es), Acceptable

0,00

No pictures to display