


RENAULT CLIO: 1PVF704

Vinnumber:	VF1CR2V4H45430759	Versionname:	
First Registrationdate:	8/08/2011	Fiscalpower:	
Expertise Mileage:	168161	Power Kw:	55
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3401
Number of doors:	3		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Aluminium		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover
Windows electric F		
Type of headlighting:	Headlighting Halogen	
Type of Lining:	Lining fabrics	
Type of climate control:	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	NOT OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear

195/50/16/88 V LightMetal				
Summer tyres:	Fr.L.	Dunlop: 1,8 mm	Fr.R.	Dunlop: 1,8 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2351,56
-------------------	---------

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display


Seat cover F L, Damaged, E - Replace	312,00
--------------------------------------	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Roof, Hail damage, PDR - Hail 125,00



Tyre F R, Damaged, E - Replace 110,40



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00




Rearview mirror R complete, Scratch(es), E - Replace 144,00



Bumper R, Broken, Le - Replace and paint 535,20



Front bumper, Bad repair, Acceptable 0,00





Wing R R, Scratch(es), LI - Repair and paint (complete) 246,56




Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 248,40



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Bad repair, Acceptable 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper grille, Unclassped, N - Fit/Remove 0,00

No pictures to display

Tailgate, Hail damage, PDR - Hail 250,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

